

List of Cameras

This is a database of USB webcams and cameras. There are **829** cameras in this database. Currently, **463** of these cameras work on Mac OS X. **Now 404 of these cameras are supported using the macam driver!** Another 18 cameras work with OEM supplied drivers. 43 cameras are supported using the USB Video Class (UVC) built-in driver found in Mac OS X 10.4.3 and later. Please report any additions or changes to this data!

Click on the colum headers to re-sort (except Notes). Click on a model name for more specific details. Note that some models might have multiple separately listed variants.

Manufacture	r Model	Notes	Status	Vendor ID	Product ID	Controller
(any)	any camera with matching IDs		should work	0x2770	0x9120	SQ905
(any)	any camera with matching IDs		should work	0x0923	0x010f	ICM532
(any)	any camera with matching IDs		should work	0x093a	0x2468	PAC207
(any)	any camera with matching IDs	Camera	depends (OEM)	0x2770	0x905c	SQ905C
(any)	any camera with matching IDs		in progress	0x06a5	0xd001	NW801
(any)	any camera with matching IDs		in progress	0x06a5	0x0000	NW800
(any)	MM353 Plako		not working (no camera)	0x81ec	0x3188	UVC
(unknown)	Cheap Chinese webcam		not working (no information)	0x06a2	0x0003	(unknown)
(unknown)	Digital Camera		not working (no documentation)	0x0979	0x0224	JL2006B
(unknown)	Digital PC Webcam CP10B3B		works	0x093a	0x2468	PAC207
(unknown)	PC Camera		works	0x093a	0x2468	PAC207
(unknown)	PC Camera		not working (no documentation)	0x106b	0x003f	(unknown)
(unknown)	PockCam 300		should work			SQ905
3Com	Home Connect	Controller	works			ViCAM
3Com	HomeConnect Lite		should work			SPCA501A
A4Tech	PK-5 (get at newegg)		works			(unknown)
A4Tech	PK-5 (get at newegg)		works			(unknown)
A4Tech	PK333MB	Supplier	works	0x0ac8	0x305b	ZC0302
Acer	built-in notebook camera		not working (no documentation)	0x0402	0x5602	M5602
Acer	Webcam		not working (no documentation)			NW801

AEL						
(Multi-Cam International)	AuraCam DC-30U	Manufacturer	works			STV680
AEL (Multi-Cam International)	AuraCam DC-31U	Manufacturer	works			STV680
AEL (Multi-Cam International)	AuraCam DC-32U	Manufacturer	works			STV680
AEL (Multi-Cam International)	DC-132U	Manufacturer	should work			SPCA504A
AEL (Multi-Cam International)	DC-31UC	Manufacturer	should work			SN9C2028AI
aGent	1.3 MP CCD Webcam (A)	Supplier	should work	0x0ac8	0x301b	ZC0301P
aGent	1.3 MP CCD Webcam (B)		not working (no documentation)	0x0402	0x5603	M5603C
Aiptek	Classic Cam	Manufacturer	works			STV680
iptek	HyperVCam Fun	Manufacturer	should work			CPiA
Aiptek	HyperVCam Fun	Manufacturer	should work			OV511+
Aiptek	HyperVCam Mobile	Manufacturer	should work			OV511+
Aiptek	Mini PenCam 1.3 MPixel	Manufacturer	works			SPCA504A
Aiptek	PalmCam USB 16MBit	Manufacturer	works			STV680
Aiptek	PalmCam USB 64MBit	Manufacturer	should work			STV680
Aiptek	PenCam 1.3M SD	Manufacturer	works	0x04fc	0x504b	SPCA504B
Aiptek	PenCam 16 MBit	Manufacturer	works			STV680
Aiptek	PenCam 400	Manufacturer	not working (no documentation)			SPCA500A
Aiptek	PenCam 64 MBit	Manufacturer	works			STV680
Aiptek	PenCam Compact	Manufacturer	works			STV680
Aiptek	PenCam Ultra/Capsule	Manufacturer	works			STV680
Aiptek	PenCam VGA 1	Manufacturer	works			STV680
Aiptek	PenCam VGA 2	Manufacturer	works			STV680
Aiptek	PenCam Voice VR2	Manufacturer	works			STV680
Aiptek	Pocket DV	Manufacturer	should work			SPCA500C
Aiptek	Pocket DV 5100M	Manufacturer	in progress	0x08ca	0x2042	SPCA536A
Aiptek	Pocket DV3300	Manufacturer	not working (no camera)	0x08ca	0x0109	ZR36430
Aiptek	PocketCam 1.3 MPixel	Manufacturer	in progress			SPCA504A
Aiptek	PocketCam 1.3 MPixel Smart	Manufacturer	should work			SPCA504A
Aiptek	PressCam	Manufacturer	should work			STV680
Aiptek	Qt Flash Cam	Manufacturer	should work			STV680
Alaris	e-snap		not working (no documentation)			(unknown)
Alaris	weeCam		not working (no documentation)			(unknown)
Alaris	weeCam Pro		not working (no documentation)			(unknown)
Alaris	Yahoo Digital Camera		not working (no documentation)			(unknown)
AMT	Pro Series USB Webcam (SPRO-5007/ STX-5007)		in progress	0x0c45	0x613b	SN9C120
Anubis	Typhoon Webcam 1.3 MPix		not working (no documentation)	0xeb1a	0x2710	EM2710
APTE	SnapScience Digital Microscope		works	0002-	0x2468	PAC207

Argus DC-1500N	Argus	DC-1500	Camera	should work			STV680
Argus DC-1312 Should work SC905 Argus DC-1730 Should work SC913C Ariston ISee Works CPIA Ariston ISee Pro works CPIA Arowana 300K CMGS Camera Manufacturer Should work SPCASDIC Arel WCU115BK Controller rand working from camera Controller partially works Ox4023 0x2600 PAC7311 Askey VC100 (350k USB Cam) Camera In progress Ox4042 Ox5602 M6602 Asus S96S laptop built-in-camera depends (UVC) 0x0563 0x1001 NW801 AverMedia Cam-Guard USB M6602 M5602 M5602 M5602 M5602 AverMedia InterCam Elle Should work 0x0728 0x001 NW801 Being DC 300 minl mol working from documentation of docume	Argus	DC-1500N		0 1			(unknown)
Argus DC-1730 sheuld work CPIA Ariston ISee works CPIA Ariston ISee Pro and tworking (no documentation) (unknown) Arowana 300K CMOS Camera Manufacturer should work SPCA501C Arwel WCU115BK Controller should work 0x93a 0x2600 PAC7311 Askey VC100 (380k USB Cam) In progress 0x06a5 0x4001 NWB01 Asus PW201 20* Monitor built-in camera depends (UVC) 0x06a5 0x4001 NWB01 Asus S96S laptop built-in camera depends (UVC) 0x06a5 0x4001 NWB01 AverMedia Cam-Guard USB in progress 0x00a2 0x5002 0x5002 0x5001 NWB01 AverMedia Inter-Cam Elite should work 0x0728 0x4001 NWB01 Benq DC 300 minl should work 0x596 0x0001 (unknown) Bental Howell EasyCam U should work 0x596 0x0002 (unknown)	Argus	DC-1510		should work			SQ905
Ariston iSee Pro Arowana 300K CMOS Camera Manufacturer Multi ISBA Aret WCU115BK Controller of Camera o	Argus	DC-1512		should work			SQ905
Arriston ISee Pro	Argus	DC-1730		should work			SQ913C
Arston See P0 Arowana 300K CMOS Camera Arowana Arowana Arowana Askey VC010 (350k USB Cam) Asus PW201 20" Monitor built-in camera Asus Sees laptop built-in camera Avalax Avalam USB-600 Avalax Ava	Ariston	iSee		works			CPiA
Arvel	Ariston	iSee Pro		0 1			(unknown)
Askey VC010 Camera not working (no camera) Askey VC100 (350k USB Cam)	Arowana	300K CMOS Camera	Manufacturer	should work			SPCA501C
Askey VC100 (350k USB Cam) in progress camera) (VPIIIIPS 0III) Asus PW201 20" Monitor built-in camera controller in progress cox06a5 oxd001 NW801 not working (no documentation) cox0402 0x5602 M5602 M5602 Avaks Avacam USB-600 should work covered in progress ox06a5 oxd001 NW801 Avarhdedia Cam-Guard USB in progress ox0728 0xd001 NW801 Averhdedia InterGam Eiltle should work covered in progress ox0728 0xd001 NW801	Arvel	WCU115BK	Controller	partially works	0x093a	0x2600	PAC7311
Asus PW201 20" Monitor built-in camera not working (no documentalitor) 0x0402 0x5602 M5602 Asus S96S laptop built-in camera depends (UVC) 0x05e3 0x f192 Cla860A Avaks AvCam USB-600 should work 0V511 OV511 AverMedia InterCam Elite should work 7 ? (unknown) Beng DC 1300 nat working (no documentation) occumentation) 0 (unknown) Beng DC 300 mini not working (no documentation) 0 (unknown) Bison Electronics Inc. BisonCam. 03, NB Pro [In MSU Wind NB U100] in progress 0x5986 0x0203 (unknown) Bodelin ProScope HR depends (UVC) 0x19ab 0x1000 (unknown) Bodeder PC ChatCam In progress 0x06a5 0x4001 NW801 Bresser BioLux AL Microscope should work 0x0e45 0x612 SN9C120 Bresser BioLux No Microscope should work 0x0e45 0x6028 SN9C102 Bre	Askey	VC010	Camera	-			(Philips old)
Asus Sy6S laptop built-in camera depends (UVC) 0x05e3 0x 1792 (GL860A Avaks AvCam USB-600 should work over the comment of the	Askey	VC100 (350k USB Cam)		in progress	0x06a5	0xd001	NW801
Avaks AvCam USB-600 should work UNTIL OV511 AverMedia Cam-Guard USB In progress 0x0728 0xd001 NW801 AverMedia InterCam Elite should work 7 7 (unknown) Bell & Howell BH-23 works 7 7 (unknown) Benq DC 1300 not working (no documentation) overking (no documentation) (unknown) Beng DC 300 mini should work - V5511 Bison EasyCam U should work - V5511 Bison Electronics Inc. BisonCam. 03, NB Pro [in MSU Wind NB U100] In progress 0x5986 0x0203 (unknown) high-speed) Bodelin ProScope HR depends (UVC) 0x19ab 0x1000 (unknown) high-speed) 0x0645 0x4010 (unknown) Bresser BioLux AL Microscope PC-Ocular in progress 0x0645 0x4010 NW01 Bresser BioLux NG Microscope Brocker should work 0x0645 0x6013 SN9C120 Bruneau Digitaci Camera should work 0x0645 0x602	Asus	PW201 20" Monitor built-in camera			0x0402	0x5602	M5602
AverMedia Cam-Guard USB in progress 0x0728 0xd001 NW801 AverMedia InterCam Elite should work 7 7 (unknown) Benq DC 1300 not working (no documentation) (unknown) (unknown) Benq DC 300 mini not working (no documentation) (unknown) (unknown) BestBuy EasyCam U should work V OV511 Bison Electronics Inc. BisonCam .03, NB Pro [in MSU Wind NB Url00] in progress 0x5986 0x0203 (unknown) (unknown) (unknown) (unknown) Bodelin ProScope HR depends (UVC) 0x19ab 0x1000 (unknown) (unknown) (unknown) (unknown) Bresser BioLux NG Microscope works 0x0645 0x4012 NW801 Brresser BioLux NG Microscope should work 0x0645 0x413c SN9C120 Bruneau Digi Tech should work 0x0645 0x413c SN9C120 Brown Digital Camera works 0x0c45 0x628 SN9C102 Canyon CN	Asus	S96S laptop built-in camera		depends (UVC)	0x05e3	0x f192	GL860A
AverMedia InterCam Elite	Avaks	AvCam USB-600		should work			OV511
AverMedia InterCam Elite	AverMedia	Cam-Guard USB		in progress	0x0728	0xd001	NW801
Benq DC 1300	AverMedia	InterCam Elite		should work			OV511
Benq DC 300 mini documentation not working (no documentation) not working (no documentation) not working (no documentation) (unknown)	Bell & Howell	BH-23		works	?	?	(unknown)
BestBuy EasyCam U	Benq	DC 1300		-			(unknown)
Bison Electronics Inc. BisonCam .03, NB Pro [in MSU Wind NB U100] in progress 0x5986 0x0203 (unknown high-speed) Bodelin ProScope HR depends (UVC) 0x19ab 0x1000 (unknown) Boeder PC ChatCam in progress 0x06a5 0xd001 NW801 Bresser BioLux AL Microscope works 0x0c45 0x613c SN9C120 Bresser BioLux NG Microscope should work 0x093a 0x2468 PAC207 Bruneau Digi Tech should work 0x0c45 0x6028 SN9C102 Brown Digital Camera works 0x0c45 0x6028 SN9C102 Camy Digital Camera should work 0x0458 0x0648 SN9C102 Canyon CN-WCAm23 (another version?) Supplier should work 0x093a 0x2468 PAC207 Canyon CN-WCAM313 Controller depends (OEM) 0x0c45 0x6270 SN9C201 Canyon CN-WCAM413 Supplier in progress 0x0ac8 0x0323 <td>Benq</td> <td>DC 300 mini</td> <td></td> <td>0 1</td> <td></td> <td></td> <td>(unknown)</td>	Benq	DC 300 mini		0 1			(unknown)
Electronics Inc. U100 In Progress Ox5986 Ox0203 Cunknown high-speed November Nove	BestBuy	EasyCam U		should work			OV511
Boeder PC ChatCam in progress 0x06a5 0xd001 NW801 Bresser BioLux AL Microscope PC-Ocular works 0x0c45 0x613c SN9C120 Bresser BioLux NG Microscope should work 0x093a 0x2468 PAC207 Bruneau Digit Tech should work SQ905 SN9C102 BTC PC-380 works 0x0c45 0x6028 SN9C102 Camex Digital Camera works 0x0c45 0x6028 SN9C102 Canyon CN-WCam23 Supplier should work VC0305 Canyon CN-WCAM313 Controller depends (0EM) 0x0c45 0x6270 SN9C201 Canyon CN-WCAM413 Supplier in progress 0x0ac8 0x0323 VC0323 Celestron Telescope eye-piece TSR350 documentation) 0xeb1a 0x2710 EM2710 Che-ez! Snap (old version) Camera depends (0EM) 0x2770 0x905c SQ905c Chicony iCam 130 (DC-3110)	Electronics			in progress	0x5986	0x0203	•
Bresser BioLux AL Microscope works 0x0c45 0x613c SN9C120 Bresser BioLux NG Microscope should work 0x093a 0x2468 PAC207 Bruneau Digi Tech should work SQ905 BTC PC-380 works 0x0c45 0x6028 SN9C102 Camex Digital Camera works SQ905 Canyon CN-WCam23 Supplier should work VC0305 Canyon CN-WCAM313 Controller depends (OEM) 0x0c45 0x6270 SN9C201 Canyon CN-WCAM313 Supplier in progress 0x0ac8 0x0323 VC0323 Canyon CNR-WCAM413 Supplier in progress 0x0ac8 0x0323 VC0323 Celestron Telescope eye-piece TSR350 not working (no documentation) 0xeb1a 0x2710 EM2710 Che-ez! Snap (old version) Snap (old version) should work 0x2770 0x905c SQ905c Chicony iCam 140 (DC-3110) not working (no inform	Bodelin	ProScope HR		depends (UVC)	0x19ab	0x1000	(unknown)
Bresser BioLux NG Microscope should work 0x093a 0x2468 PAC207 Bruneau Digi Tech should work SQ905 BTC PC-380 works 0x0c45 0x6028 SN9C102 Camex Digital Camera works SQ905 Canyon CN-WCam23 Supplier should work VC0305 Canyon CN-WCAM313 Controller depends (OEM) 0x0c45 0x6270 SN9C201 Canyon CN-WCAM313 Supplier in progress 0x0ac8 0x0323 VC0323 Celestron Telescope eye-piece TSR350 not working (no documentation) 0xeb1a 0x2710 EM2710 Che-ez! Snap (new version) Camera depends (OEM) 0x2770 0x905c SQ905c Che-ez! Snap (old version) should work 0x2770 0x9120 SQ905c Chicony iCam 130 (DC-3110) works (unknown) Chicony iCam 340 (DC-4120) works 0x05a9 0x8519 OV519 <t< td=""><td>Boeder</td><td>PC ChatCam</td><td></td><td>in progress</td><td>0x06a5</td><td>0xd001</td><td>NW801</td></t<>	Boeder	PC ChatCam		in progress	0x06a5	0xd001	NW801
Bruneau Digi Tech should work SQ905 BTC PC-380 works 0x0c45 0x6028 SN9C102 Camex Digital Camera works SQ905 Canyon CN-WCam23 Supplier should work VC0305 Canyon CN-WCAM313 Controller depends (OEM) 0x0c45 0x6270 SN9C201 Canyon CNR-WCAM413 Supplier in progress 0x0ac8 0x0323 VC0323 Celestron Telescope eye-piece TSR350 not working (no documentation) 0xeb1a 0x2710 EM2710 Che-ez! Snap (new version) Camera depends (OEM) 0x2770 0x905c SQ905c Che-ez! Snap (old version) should work 0x2770 0x9120 SQ905c Chicony iCam 140 (DC-3110) works (unknown) Chicony iCam 340 (DC-4120) works 0x05a9 0x8519 OV519 Chicony iCam 540 (DC-4130) not working (no information) (unknown) Chicony	Bresser	BioLux AL Microscope PC-Ocular		works	0x0c45	0x613c	SN9C120
BTC PC-380 works 0x0c45 0x6028 SN9C102 Camex Digital Camera works SQ905 Canyon CN-WCam23 Supplier should work VC0305 Canyon CN-WCam23 (another version?) should work 0x093a 0x2468 PAC207 Canyon CN-WCAM313 Controller depends (OEM) 0x0c45 0x6270 SN9C201 Canyon CN-WCAM413 Supplier in progress 0x0ac8 0x0323 VC0323 Celestron Telescope eye-piece TSR350 not working (no documentation) 0xeb1a 0x2710 EM2710 Che-ez! Snap (new version) Camera depends (OEM) 0x2770 0x905c SQ905c Che-ez! Snap (old version) works 0x2770 0x9120 SQ905c Chicony iCam 130 (DC-3110) works (unknown) Chicony iCam 330 (DC-3120) works 0x05a9 0x8519 0y519 Chicony iCam 530 (DC-3150) not working (no information)	Bresser	BioLux NG Microscope		should work	0x093a	0x2468	PAC207
Camex Digital Camera works SQ905 Canyon CN-WCam23 Supplier should work VC0305 Canyon CN-WCam23 (another version?) should work 0x093a 0x2468 PAC207 Canyon CN-WCAM313 Controller depends (OEM) 0x0c45 0x6270 SN9C201 Canyon CNR-WCAM413 Supplier in progress 0x0ac8 0x0323 VC0323 Celestron Telescope eye-piece TSR350 not working (no documentation) 0xeb1a 0x2710 EM2710 Che-ez! Snap (new version) Camera depends (OEM) 0x2770 0x905c SQ905c Che-ez! Snap (old version) should work 0x2770 0x9120 SQ905 Chicony iCam 130 (DC-3110) works (unknown) Chicony iCam 330 (DC-3120) works 0x05a9 0x8519 0V519 Chicony iCam 530 (DC-3150) not working (no information) (unknown) Chicony iCam 540 (DC-4130) not working (no information) (Bruneau	Digi Tech		should work			SQ905
Canyon CN-WCam23 Supplier should work VC0305 Canyon CN-WCam23 (another version?) should work 0x093a 0x2468 PAC207 Canyon CN-WCAM313 Controller depends (OEM) 0x0c45 0x6270 SN9C201 Canyon CNR-WCAM413 Supplier in progress 0x0ac8 0x0323 VC0323 Celestron Telescope eye-piece TSR350 not working (no documentation) 0xeb1a 0x2710 EM2710 Che-ez! Snap (new version) Camera depends (OEM) 0x2770 0x905c SQ905c Che-ez! Snap (old version) should work 0x2770 0x9120 SQ905 Chicony ICam 130 (DC-3110) works (unknown) Chicony ICam 330 (DC-4110) works 0x05a9 0x8519 0V519 Chicony ICam 530 (DC-3150) not working (no information) (unknown) Chicony ICam 540 (DC-4130) not working (no information) (unknown)	BTC	PC-380		works	0x0c45	0x6028	SN9C102
Canyon CN-WCam23 (another version?) should work 0x093a 0x2468 PAC207 Canyon CN-WCAM313 Controller depends (OEM) 0x0c45 0x6270 SN9C201 Canyon CNR-WCAM413 Supplier in progress 0x0ac8 0x0323 VC0323 Celestron Telescope eye-piece TSR350 not working (no documentation) 0xeb1a 0x2710 EM2710 Che-ez! Snap (new version) Camera depends (OEM) 0x2770 0x905c SQ905c Che-ez! Snap (old version) should work 0x2770 0x9120 SQ905 Chicony iCam 130 (DC-3110) works (unknown) Chicony iCam 340 (DC-4110) works (unknown) Chicony iCam 340 (DC-4120) works 0x05a9 0x8519 OV519 Chicony iCam 540 (DC-4130) not working (no information) (unknown) Chicony iCam 540 (DC-4130) information) (unknown)	Camex	Digital Camera		works			SQ905
Canyon CN-WCAM313 Controller depends (OEM) 0x0c45 0x6270 SN9C201 Canyon CNR-WCAM413 Supplier in progress 0x0ac8 0x0323 VC0323 Celestron Telescope eye-piece TSR350 not working (no documentation) 0xeb1a 0x2710 EM2710 Che-ez! Snap (new version) Camera depends (OEM) 0x2770 0x905c SQ905c Che-ez! Snap (old version) should work 0x2770 0x9120 SQ905 Chicony iCam 130 (DC-3110) works (unknown) Chicony iCam 330 (DC-4110) works (unknown) Chicony iCam 340 (DC-4120) works 0x05a9 0x8519 OV519 Chicony iCam 530 (DC-3150) not working (no information) (unknown) Chicony iCam 540 (DC-4130) not working (no information) (unknown)	Canyon	CN-WCam23	Supplier	should work			VC0305
Canyon CNR-WCAM413 Supplier in progress 0x0ac8 0x0323 VC0323 Celestron Telescope eye-piece TSR350 not working (no documentation) 0xeb1a 0x2710 EM2710 Che-ez! Snap (new version) Camera depends (OEM) 0x2770 0x905c SQ905c Che-ez! Snap (old version) should work 0x2770 0x9120 SQ905 Chicony iCam 130 (DC-3110) works (unknown) Chicony iCam 330 (DC-3120) works (unknown) Chicony iCam 340 (DC-4120) works 0x05a9 0x8519 OV519 Chicony iCam 530 (DC-3150) not working (no information) (unknown) Chicony iCam 540 (DC-4130) not working (no information) (unknown)	Canyon	CN-WCam23 (another version?)		should work	0x093a	0x2468	PAC207
Celestron Telescope eye-piece TSR350 not working (no documentation)	Canyon	CN-WCAM313	Controller	depends (OEM)	0x0c45	0x6270	SN9C201
Celestron Telescope eye-piece TSR350 Che-ez! Snap (new version) Che-ez! Snap (old version) Chicony iCam 130 (DC-3110) Chicony iCam 330 (DC-3120) Chicony iCam 340 (DC-4120) Chicony iCam 530 (DC-3150) Chicony iCam 540 (DC-4130)	Canyon	CNR-WCAM413	Supplier	in progress	0x0ac8	0x0323	VC0323
Che-ez! Snap (old version) should work 0x2770 0x9120 SQ905 Chicony iCam 130 (DC-3110) works (unknown) Chicony iCam 140 (DC-4110) not working (no information) (unknown) Chicony iCam 330 (DC-3120) works 0x05a9 0x8519 OV519 Chicony iCam 530 (DC-3150) not working (no information) (unknown) Chicony iCam 540 (DC-4130) not working (no information) (unknown)	Celestron	Telescope eye-piece TSR350			0xeb1a	0x2710	EM2710
Chicony iCam 130 (DC-3110) works (unknown) Chicony iCam 140 (DC-4110) not working (no information) (unknown) Chicony iCam 330 (DC-3120) works (unknown) Chicony iCam 340 (DC-4120) works 0x05a9 0x8519 OV519 Chicony iCam 530 (DC-3150) not working (no information) (unknown) Chicony iCam 540 (DC-4130) not working (no information) (unknown)	Che-ez!	Snap (new version)	Camera	depends (OEM)	0x2770	0x905c	SQ905C
Chicony iCam 140 (DC-4110) not working (no information) (unknown) Chicony iCam 330 (DC-3120) works (unknown) Chicony iCam 340 (DC-4120) works 0x05a9 0x8519 0V519 Chicony iCam 530 (DC-3150) not working (no information) (unknown) Chicony iCam 540 (DC-4130) not working (no information) (unknown)	Che-ez!	Snap (old version)		should work	0x2770	0x9120	SQ905
Chicony iCam 140 (DC-4110) information) (unknown) Chicony iCam 330 (DC-3120) works (unknown) Chicony iCam 340 (DC-4120) works 0x05a9 0x8519 0V519 Chicony iCam 530 (DC-3150) not working (no information) (unknown) Chicony iCam 540 (DC-4130) not working (no information) (unknown)	Chicony	iCam 130 (DC-3110)		works			(unknown)
Chicony iCam 340 (DC-4120) works 0x05a9 0x8519 OV519 Chicony iCam 530 (DC-3150) not working (no information) (unknown) Chicony iCam 540 (DC-4130) (unknown)	Chicony	iCam 140 (DC-4110)		-			(unknown)
Chicony iCam 530 (DC-3150) not working (no information) (unknown) Chicony iCam 540 (DC-4130) not working (no information) (unknown)	Chicony	iCam 330 (DC-3120)		works			(unknown)
Chicony iCam 530 (DC-3150) information) (unknown) Chicony iCam 540 (DC-4130) not working (no information) (unknown)	Chicony	iCam 340 (DC-4120)		works	0x05a9	0x8519	OV519
Chicony ICam 540 (DC-4130) information) (unknown)	Chicony	iCam 530 (DC-3150)		-			(unknown)
Chicony TwinkleCam (DC-2110) in progress 0x06a5 0xd001 NW801	Chicony	iCam 540 (DC-4130)		0 1			(unknown)
	Chicony	TwinkleCam (DC-2110)		in progress	0x06a5	0xd001	NW801

Chicory TwinkleCam Pro (DC-2120) Ind morking (no information) County Count	Chicony	TwinkleCam (DC-2110A)		works	0x0c45	0x600d	SN9C101
Cibox PC-188 Should work Dx093a 0x2468 PAC207	,	,			0,00043	0,0000	
Cisco				•	0,0020	0,2440	,
Cince							
Conceptronic ChalCam (CCHATCAM) Conceptronic Video Pro (CVIDEOPRO USB Webcam CCD) Conceptronic Video Pro (CVIDEOPRO USB Webcam CCD) Concerd Eye-Q Easy Conceptronic Video Pro (CVIDEOPRO USB Webcam CCD) Concerd Eye-Q Easy Should work Should	CISCO	vt camera ii		• • • • • •	UXU460	UXU8C7	SPCA525A
Conceptronic	Clone	11086 webcam		-	0x0c45	0x612f	SN9C110
Conceptronic FunCam	Conceptronic	ChatCam (CCHATCAM)	Supplier	works	0x0ac8	0x0302	VC0302
Conceptronic Video Pro (CVIDEOPRO USB Webcam CCD)	Conceptronic	CMOBICAM	Camera	should work			ICM532
Concord Eye-Q Duo	Conceptronic	FunCam		should work	0x093a	0x2468	PAC207
Concerd Eye-Q Easy	Conceptronic	Video Pro (CVIDEOPRO USB Webcam CCD)		in progress	0x06a5	0xd001	NW801
Conexant Ezonics P10UC	Concord	Eye-Q Duo		should work			SQ905
Concentrate Exonics P100C	Concord	Eye-Q Easy		should work			SQ905
Technologies	Conexant	Ezonics P10UC		. .			(unknown)
Creative Labs Livel Cam (VF0350) in progress 0x401e 0x4009 OV519 Creative Labs Livel Cam Notebook (VF0470) works 0x041e 0x4061 0x4051 VC0301P Creative Labs Livel Cam Notebook Pro (VF0400) works 0x041e 0x4051 VC0301P Creative Labs Livel Cam Notebook Ultra (VF0310) not working (no documentation) 0x041e 0x4055 (unknown) Creative Labs Livel Cam Optia (VF0270) depends (UVC) 0x041e 0x4057 (unknown) Creative Labs Livel Cam Optia AF (VF0280) depends (UVC) 0x041e 0x4058 (unknown) Creative Labs Livel Cam Video IM (Skype Edition) not working (no documentation) (unknown) Creative Labs Livel Cam Video IM (VF0220) Supplier should work 0x041e 0x4065 (unknown) Creative Labs		USB Mini Web Cam (CP-MPC-01)		works	0x093a	0x2468	PAC207
Creative Labs Live! Cam Chat IM (VF0530) depends (UVC) 0x041e? 0x4068 0V519	Creative Labs	CardCam		-	0x041e	0x4016	SMaL
Creative Labs Livel Cam Notebook (VF0470) works 0x041e 0x4068 OV519 Creative Labs Livel Cam Notebook Pro (VF0250) Supplier works 0x041e 0x4051 VC0301P Creative Labs Livel Cam Notebook Pro (VF0400) works 0x041e 0x4061 OV519 Creative Labs Livel Cam Notebook Ultra (VF0210) documentation 0x041e 0x405b (unknown) Creative Labs Livel Cam Optia AF (VF0280) depends (UVC) 0x041e 0x4058 (unknown) Creative Labs Livel Cam Optia AF (VF0280) depends (UVC) 0x041e 0x4058 (unknown) Creative Labs Livel Cam Optia AF (VF0280) depends (UVC) 0x041e 0x4058 (unknown) Creative Labs Livel Cam Optia AF (VF0380) depends (UVC) 0x041e 0x4065 (unknown) Creative Labs Livel Cam Video IM (Skype Edition) not working (no Information) 0x041e 0x4065 (unknown) Creative Labs Livel Cam Video IM (VF0220) Supplier should work 0x041e 0x4067 0x0519<	Creative Labs	Live! Cam (VF0350)		in progress	0x041e	0x4060	OV519
Creative Labs Livel Cam Notebook Pro (VF0250) Supplier works 0x041e 0x4051 VC0301P Creative Labs Livel Cam Notebook Pro (VF0400) works 0x041e 0x4061 OV519 Creative Labs Livel Cam Notebook Ultra (VF0310) not working (no documentation) 0x041e 0x405b (unknown) Creative Labs Livel Cam Optia AF (VF0280) depends (UVC) 0x041e 0x4057 (unknown) Creative Labs Livel Cam Optia AF (VF0560) depends (UVC) 0x041e 0x4058 (unknown) Creative Labs Livel Cam Optia AF (VF0560) depends (UVC) 0x041e 0x4065 (unknown) Creative Labs Livel Cam Video IM (VF0380) depends (UVC) 0x041e 0x4065 (unknown) Creative Labs Livel Cam Video IM (VF0220) Supplier should work 0x041e 0x4053 VC0301P Creative Labs Livel Cam Video IM Pro (VF0230) documentation) 0x041e 0x4067 Ov519 Creative Labs Livel Cam Video IM Pro (VF0260L4) depends (UVC) 0x041e 0x4063	Creative Labs	Live! Cam Chat IM (VF0530)		depends (UVC)	0x041e?	0x40??	UVC
Creative Labs Live! Cam Notebook Pro (VF0400) works 0x041e 0x4061 OV519 Creative Labs Live! Cam Notebook Ultra (VF0310) not working (no documentation) 0x041e 0x405b (unknown) Creative Labs Live! Cam Optia (VF0270) depends (UVC) 0x041e 0x4057 (unknown) Creative Labs Live! Cam Optia AF (VF0280) depends (UVC) 0x041e 0x4058 (unknown) Creative Labs Live! Cam Optia AF (VF0560) depends (UVC) 0x041e 0x4065 (unknown) Creative Labs Live! Cam Optia AF (VF0560) depends (UVC) 0x041e 0x4065 (unknown) Creative Labs Live! Cam Optia Pro (VF0380) should work information 0x041e 0x4065 (unknown) Creative Labs Live! Cam Video IM (VF0220) Supplier should work information 0x041e 0x4065 VC0301P Creative Labs Live! Cam Video IM (VF0220) Supplier should work information 0x041e 0x4067 OV519 Creative Labs Live! Cam Video IM Pro (VF0230) not working (no depends (UVC) <t< td=""><td>Creative Labs</td><td>Live! Cam Notebook (VF0470)</td><td></td><td>works</td><td>0x041e</td><td>0x4068</td><td>OV519</td></t<>	Creative Labs	Live! Cam Notebook (VF0470)		works	0x041e	0x4068	OV519
Creative Labs Livel Cam Notebook Ultra (VF0310)	Creative Labs	Live! Cam Notebook Pro (VF0250)	Supplier	works	0x041e	0x4051	VC0301P
Creative Labs Livel Cam Optia (VF0270) documentation) Creative Labs Livel Cam Optia (VF0270) depends (UVC) 0x041e 0x4057 (unknown) Creative Labs Livel Cam Optia AF (VF0280) depends (UVC) 0x041e 0x4058 (unknown) Creative Labs Livel Cam Optia AF (VF0560) depends (UVC) 0x041e 0x4065 (unknown) Creative Labs Livel Cam Optia Pro (VF0380) depends (UVC) 0x041e 0x4065 (unknown) Creative Labs Livel Cam Video IM (Skype Edition) not working (no information) Creative Labs Livel Cam Video IM (VF0220) Supplier should work 0x041e 0x4065 (unknown) Creative Labs Livel Cam Video IM (VF0350) in progress 0x041e 0x4067 OV519 Creative Labs Livel Cam Video IM Pro (VF0230) not working (no documentation) Creative Labs Livel Cam Video IM Pro (VF0230) depends (UVC) 0x041e 0x4053 M5603C Creative Labs Livel Cam Video IM Pro (VF0260L4) depends (UVC) 0x041e 0x4065 (unknown) Creative Labs Livel Cam Video IM Pro (VF0410) depends (UVC) 0x041e 0x4065 UVC Creative Labs Livel Cam Video IM/Video Chat (VF0540) works 0x041e 0x4066 UVC Creative Labs Livel Cam Vista IM (VF0260) works 0x041e 0x4065 UVC Creative Labs Livel Cam Vista IM (VF0420) works 0x041e 0x4064 OV519 Creative Labs Livel Cam Vista IM (VF0420) works 0x041e 0x4064 OV519 Creative Labs PC-CAM 300 not working (no camera) Creative Labs PC-CAM 550 (PD1020) 0x4065 not working (no camera) Creative Labs PC-CAM 600 not working (no camera) Creative Labs PC-CAM 880 [0x4025 mass storage] 0x041e 0x404f (unknown) Creative Labs PC-CAM 950 Slim 0x4045 not working (no documentation)	Creative Labs	Live! Cam Notebook Pro (VF0400)		works	0x041e	0x4061	OV519
Creative Labs Livel Cam Optia AF (VF0280) depends (UVC) 0x041e 0x4058 (unknown) Creative Labs Livel Cam Optia AF (VF0560) depends (UVC) 0x041e ?? (unknown) Creative Labs Livel Cam Optia AF (VF0560) depends (UVC) 0x041e ?? (unknown) Creative Labs Livel Cam Video IM (Skype Edition) not working (no information) Creative Labs Livel Cam Video IM (VF0220) Supplier should work 0x041e 0x4053 VC0301P Creative Labs Livel Cam Video IM (VF0250) in progress 0x041e 0x4055 M5603C Creative Labs Livel Cam Video IM Pro (VF0230) documentation) Creative Labs Livel Cam Video IM Pro (VF0230) depends (UVC) 0x041e 0x4055 M5603C Creative Labs Livel Cam Video IM Pro (VF0260L4) depends (UVC) 0x041e 0x4063 (unknown) Creative Labs Livel Cam Video IM Pro (VF0410) depends (UVC) 0x041e 0x4066 UVC Creative Labs Livel Cam Video IM Pro (VF0410) depends (UVC) 0x041e 0x4066 UVC Creative Labs Livel Cam Video IM/Video Chat (VF0540) works 0x041e 0x4069 OV519 Creative Labs Livel Cam Video IM (VF0420) works 0x041e 0x4062 OV519 Creative Labs Livel Cam Video IM (VF0420) works 0x041e 0x4064 OV519 Creative Labs PC-CAM 300 not working (no camera) Creative Labs PC-CAM 300 SPCA500A Creative Labs PC-CAM 800 [0x4025 mass storage] not working (no camera) Creative Labs PC-CAM 800 [0x4025 mass storage] Creative Labs PC-CAM 950 Slim 0x041e 0x404f (unknown)	Creative Labs	Live! Cam Notebook Ultra (VF0310)		.	0x041e	0x405b	(unknown)
Creative Labs Livel Cam Optia AF (VF0560) Creative Labs Livel Cam Optia Pro (VF0380) Creative Labs Livel Cam Video IM (Skype Edition) Creative Labs Livel Cam Video IM (VF0220) Creative Labs Livel Cam Video IM (VF0350) Creative Labs Livel Cam Video IM (VF0350) Creative Labs Livel Cam Video IM (VF0230) Creative Labs Livel Cam Video IM Pro (VF0230) Creative Labs Livel Cam Video IM Pro (VF0230) Creative Labs Livel Cam Video IM Pro (VF0260L4) Creative Labs Livel Cam Video IM Pro (VF0260L4) Creative Labs Livel Cam Video IM Pro (VF0410) Creative Labs Livel Cam Video IM Pro (VF0410) Creative Labs Livel Cam Video IM Video Chat (VF0540) Creative Labs Livel Cam Vista IM (VF0260) Creative Labs Livel Cam Vista IM (VF0420) Creative Labs Creative La	Creative Labs	Live! Cam Optia (VF0270)		depends (UVC)	0x041e	0x4057	(unknown)
Creative Labs Livel Cam Optia Pro (VF0380) depends (UVC)	Creative Labs	Live! Cam Optia AF (VF0280)		depends (UVC)	0x041e	0x4058	(unknown)
Creative Labs Livel Cam Video IM (Skype Edition) Creative Labs Livel Cam Video IM (VF0220) Creative Labs Livel Cam Video IM (VF0350) Creative Labs Livel Cam Video IM (VF0350) Creative Labs Livel Cam Video IM (VF0350) Creative Labs Livel Cam Video IM Pro (VF0230) Creative Labs Livel Cam Video IM Pro (VF0230) Creative Labs Livel Cam Video IM Pro (VF0260L4) Creative Labs Livel Cam Video IM Pro (VF0260L4) Creative Labs Livel Cam Video IM Pro (VF0410) Creative Labs Livel Cam Video IM Pro (VF0410) Creative Labs Livel Cam Video IM Video Chat (VF0540) Creative Labs Livel Cam Video IM Video Chat (VF0540) Creative Labs Livel Cam Vista IM (VF0260) Creative Labs Livel Cam Vista IM (VF0420) Creative Labs Livel Cam Voice (VF0170) Creative Labs PC-CAM 300 Creative Labs PC-CAM 550 (PD1020) Creative Labs PC-CAM 880 [0x4025 mass storage] Creative Labs PC-CAM 950 Slim Inot working (no documentation) Ox041e Ox404f (unknown) Ox041e Ox4024 ZR36430 Creative Labs PC-CAM 950 Slim Ox041e Ox404f (unknown)	Creative Labs	Live! Cam Optia AF (VF0560)		depends (UVC)	0x041e	??	(unknown)
Creative Labs Live! Cam Video IM (VF0220) Supplier should work	Creative Labs	Live! Cam Optia Pro (VF0380)		depends (UVC)	0x041e	0x4065	(unknown)
Creative Labs Live! Cam Video IM (VF0230) in progress 0x041e 0x4067 OV519 Creative Labs Live! Cam Video IM Pro (VF0230) not working (no documentation) 0x041e 0x4055 M5603C Creative Labs Live! Cam Video IM Pro (VF0260L4) depends (UVC) 0x041e 0x4063 (unknown) Creative Labs Live! Cam Video IM Pro (VF0410) depends (UVC) 0x041e 0x4066 UVC Creative Labs Live! Cam Video IM/Video Chat (VF0540) works 0x041e 0x4069 OV519 Creative Labs Live! Cam Vista IM (VF0260) works 0x041e 0x4062 OV519 Creative Labs Live! Cam Vista IM (VF0420) works 0x041e 0x4064 OV519 Creative Labs Live! Cam Voice (VF0170) not working (no camera) 0x041e 0x4045 M5603C Creative Labs PC-CAM 300 not working (no camera) Creative Labs PC-CAM 550 (PD1020) not working (no camera) Creative Labs PC-CAM 880 [0x4025 mass storage] not working (no documentation) 0x041e 0x404f (unknown) Creative Labs PC-CAM 950 Slim 0x041e Dx404f (unknown)	Creative Labs	Live! Cam Video IM (Skype Edition)		3 ((unknown)
Creative Labs Live! Cam Video IM Pro (VF0230) Creative Labs Live! Cam Video IM Pro (VF0260L4) Creative Labs Live! Cam Video IM Pro (VF0260L4) Creative Labs Live! Cam Video IM Pro (VF0410) Creative Labs Live! Cam Video IM Pro (VF0410) Creative Labs Live! Cam Video IM Pro (VF0410) Creative Labs Live! Cam Video IM/Video Chat (VF0540) Creative Labs Live! Cam Vista IM (VF0260) Creative Labs Live! Cam Vista IM (VF0260) Creative Labs Live! Cam Voice (VF0170) Creative Labs Live! Cam Voice (VF0170) Creative Labs PC-CAM 300 Creative Labs PC-CAM 550 (PD1020) Creative Labs PC-CAM 880 [0x4025 mass storage] Creative Labs PC-CAM 950 Slim Creat	Creative Labs	Live! Cam Video IM (VF0220)	Supplier	should work	0x041e	0x4053	VC0301P
Creative Labs Live! Cam Video IM Pro (VF0230) Creative Labs Live! Cam Video IM Pro (VF0260L4) Creative Labs Live! Cam Video IM Pro (VF0260L4) Creative Labs Live! Cam Video IM Pro (VF0410) Creative Labs Live! Cam Video IM/Video Chat (VF0540) Creative Labs Live! Cam Vista IM (VF0260) Creative Labs Live! Cam Vista IM (VF0260) Creative Labs Live! Cam Vista IM (VF0420) Creative Labs Live! Cam Vista IM (VF0420) Creative Labs Live! Cam Voice (VF0170) Creative Labs PC-CAM 300 Creative Labs PC-CAM 550 (PD1020) Creative Labs PC-CAM 600 Creative Labs PC-CAM 880 [0x4025 mass storage] Creative Labs PC-CAM 950 Slim	Creative Labs	Live! Cam Video IM (VF0350)		in progress	0x041e	0x4067	OV519
Creative Labs Live! Cam Video IM Pro (VF0260L4) depends (UVC) 0x041e 0x4063 (unknown) Creative Labs Live! Cam Video IM Pro (VF0410) depends (UVC) 0x041e 0x4056 UVC Creative Labs Live! Cam Video IM/Video Chat (VF0540) works 0x041e 0x4069 OV519 Creative Labs Live! Cam Vista IM (VF0260) works 0x041e 0x4052 OV519 Creative Labs Live! Cam Vista IM (VF0420) works 0x041e 0x4064 OV519 Creative Labs Live! Cam Voice (VF0170) not working (no camera) 0x041e 0x4045 M5603C Creative Labs PC-CAM 300 not working (no camera) not working (no documentation) not working (no camera) Creative Labs PC-CAM 600 not working (no camera) Creative Labs PC-CAM 880 [0x4025 mass storage] not working (no documentation) not working (no documentation) not working (no documentation) not working (no documentation) 0x041e 0x4024 ZR36430 Creative Labs PC-CAM 950 Slim not working (no documentation) 0x041e 0x404f (unknown)	Creative Labs	Live! Cam Video IM Pro (VF0230)		not working (no	0x041e	0x4055	M5603C
Creative Labs Live! Cam Video IM Pro (VF0410) depends (UVC) 0x041e 0x4056 UVC Creative Labs Live! Cam Video IM/Video Chat (VF0540) works 0x041e 0x4069 OV519 Creative Labs Live! Cam Vista IM (VF0260) works 0x041e 0x4052 OV519 Creative Labs Live! Cam Vista IM (VF0420) works 0x041e 0x4064 OV519 Creative Labs Live! Cam Voice (VF0170) not working (no camera) 0x041e 0x4045 M5603C Creative Labs PC-CAM 300 not working (no camera) SPCA500A Creative Labs PC-CAM 550 (PD1020) not working (no documentation) not working (no camera) Creative Labs PC-CAM 880 [0x4025 mass storage] not working (no documentation) 0x041e 0x4024 ZR36430 Creative Labs PC-CAM 950 Slim not working (no documentation) 0x041e 0x404f (unknown)	Creative Labs	Livel Cam Video IM Pro (VF0260L4)		•	0x041e	0x4063	(unknown)
Creative Labs Live! Cam Video IM/Video Chat (VF0540) works 0x041e 0x4069 OV519 Creative Labs Live! Cam Vista IM (VF0260) works 0x041e 0x4052 OV519 Creative Labs Live! Cam Vista IM (VF0420) works 0x041e 0x4064 OV519 Creative Labs Live! Cam Voice (VF0170) not working (no camera) 0x041e 0x4045 M5603C Creative Labs PC-CAM 300 not working (no camera) SPCA500A Creative Labs PC-CAM 550 (PD1020) not working (no documentation) not working (no camera) Creative Labs PC-CAM 880 [0x4025 mass storage] not working (no documentation) 0x041e 0x404f (unknown) Creative Labs PC-CAM 950 Slim 0x041e 0x404f (unknown)		· · · ·					,
Creative Labs Live! Cam Vista IM (VF0260) works 0x041e 0x4052 OV519 Creative Labs Live! Cam Vista IM (VF0420) works 0x041e 0x4064 OV519 Creative Labs Live! Cam Voice (VF0170) not working (no camera) not working (no camera) Creative Labs PC-CAM 300 not working (no documentation) Creative Labs PC-CAM 550 (PD1020) not working (no documentation) Creative Labs PC-CAM 600 not working (no camera) Creative Labs PC-CAM 880 [0x4025 mass storage] not working (no documentation) Creative Labs PC-CAM 950 Slim not working (no documentation) Creative Labs PC-CAM 950 Slim not working (no documentation) Creative Labs PC-CAM 950 Slim not working (no documentation)		· · ·					
Creative Labs Live! Cam Vista IM (VF0420) Creative Labs Live! Cam Voice (VF0170) Creative Labs PC-CAM 300 Creative Labs PC-CAM 550 (PD1020) Creative Labs PC-CAM 600 Creative Labs PC-CAM 880 [0x4025 mass storage] Creative Labs PC-CAM 950 Slim works 0x041e 0x4064 OV519 not working (no camera) not working (no documentation) not working (no camera) not working (no camera) Nov041e 0x404f MX88L60UC SPCA500A Creative Labs PC-CAM 880 [0x4025 mass storage] not working (no documentation) not working (no documentation) Ox041e 0x402f ZR36430 Creative Labs PC-CAM 950 Slim							
Creative Labs Live! Cam Voice (VF0170) Creative Labs PC-CAM 300 Creative Labs PC-CAM 550 (PD1020) Creative Labs PC-CAM 600 Creative Labs PC-CAM 880 [0x4025 mass storage] Creative Labs PC-CAM 950 Slim not working (no camera) not working (no documentation) not working (no documentation) not working (no documentation) 0x041e 0x402f ZR36430 Creative Labs PC-CAM 950 Slim							
Creative Labs PC-CAM 300		•		not working (no			
Creative Labs PC-CAM 550 (PD1020) Creative Labs PC-CAM 600 Creative Labs PC-CAM 880 [0x4025 mass storage] Creative Labs PC-CAM 950 Slim not working (no camera) not working (no documentation)	Creative Labs	PC-CAM 300		not working (no			SPCA500A
Creative Labs PC-CAM 880 [0x4025 mass storage] Creative Labs PC-CAM 880 [0x4025 mass storage] Creative Labs PC-CAM 950 Slim camera) not working (no documentation) not working (no documentation) 0x041e 0x4024 ZR36430 0x041e 0x404f (unknown)	Creative Labs	PC-CAM 550 (PD1020)		.	0x041e	0x400f	MX88L60UC
Creative Labs PC-CAM 880 [0x4025 mass storage] documentation not working (no documentation) 0x041e 0x4024 ZR36430 0x041e 0x404f (unknown)	Creative Labs	PC-CAM 600		. .			SPCA504A
documentation) documentation	Creative Labs	PC-CAM 880 [0x4025 mass storage]		.	0x041e	0x4024	ZR36430
Creative Labs Vibra WebCam (PD1100) should work 0x041e 0x403b SPCA561A	Creative Labs	PC-CAM 950 Slim		-	0x041e	0x404f	(unknown)
	Creative Labs	Vibra WebCam (PD1100)		should work	0x041e	0x403b	SPCA561A

Creative Labs	Video Blaster Webcam 1		not working (no documentation)			(unknown)
Creative Labs	Video Blaster Webcam 2		works			CPiA
Creative Labs	Video Blaster Webcam 3		works			OV511
Creative Labs	Video Blaster Webcam 5	Camera	should work			SAA8116HL
Creative Labs	WebCam		not working (no documentation)			(unknown)
Creative Labs	Webcam 5 (newer model)		not working (no camera)			(unknown)
Creative Labs	Webcam 5 (older model)	Camera	should work			SAA8116HL
Creative Labs	WebCam CT6840		works			OV511
Creative Labs	WebCam GO		not working (no camera)	0x1046	0x9967	W9967CF
Creative Labs	WebCam GO ES		not working (no documentation)	0x041e	0x4005	MX88L60UC
Creative Labs	WebCam Go Mini (PD0070)		in progress	0x041e	0x4007	STV680
Creative Labs	WebCam GO Plus [CT7510 or CT7150]		not working (no camera)	0x041e	0x4003	W9967CF
Creative Labs	WebCam Instant (PD620/VF0040)	Supplier	works	0x041e	0x4034	ZC0301
Creative Labs	WebCam Instant Skype Edition	Supplier	works	0x041e	0x4034	ZC0301
Creative Labs	WebCam Live! (VF0050) (A)	Supplier	works	0x041e	0x4036	ZC0301P
Creative Labs	WebCam Live! (VF0050) (B)	Supplier	in progress	0x041e	0x4029	VC0301P
Creative Labs	WebCam Live! Effects		not working (no documentation)	0x041e	0x4039	M5602
Creative Labs	WebCam Live! Motion (VF0150)		in progress	0x041e	0x4041	SQ930B
Creative Labs	WebCam Live! Pro		not working (no documentation)	0x041e	0x4038	SQ930C
Creative Labs	WebCam Live! Ultra (VF0060)		in progress	0x041e	0x403c	SQ930B
Creative Labs	WebCam Live! Ultra for Notebooks (VF0070)		in progress	0x041e	0x403d	SQ930B
Creative Labs	WebCam Mobile EGS (PD1090 or PD1190?)	Supplier	should work	0x041e	0x4017	ZC0301P
Creative Labs	WebCam Notebook (PD1170) [A]	Supplier	works	0x041e	0x401f	ZC0301P
Creative Labs	Webcam Notebook (PD1170) [B]		in progress	0x0572	0x0041	CX11646
Creative Labs	WebCam Notebook (PD1171)	Supplier	should work	0x041e	0x401f	ZC0301P
Creative Labs	WebCam NX (PD1110)	Supplier	works	0x041e	0x401c	ZC0301
Creative Labs	WebCam NX Pro (PD1130)	Supplier	works	0x041e	0x401e	ZC0301P
Creative Labs	WebCam NX Pro (PD1131)	Supplier	should work	0x041e	0x403a	ZC0301P
Creative Labs	WebCam NX Ultra (PD1120)		works	0x041e	0x401d	SPCA505B
Creative Labs	Webcam Plus (CT6840)		should work	0x05a9	0xa511	OV511+
Creative Labs	WebCam Pro (PD1030)	Camera	works	0x05a9	0xa511	OV511+
Creative Labs	WebCam Pro Ex	Controller	works			SAA8116HL
Creative Labs	WebCam Vista (A) (PD1100)		should work	0x041e	0x4018	SPCA508A
Creative Labs	WebCam Vista (B) (PD1100)		should work	0x041e	0x401a	SPCA561A
Creative Labs	WebCam Vista (C) (VF0010)		should work	0x041e	0x403b	SPCA561A
Creative Labs	WebCam Vista (D) (VF0330)		works	0x041e	0x405f	OV519
Creative Labs	WebCam Vista Plus		works	0x041e	0x4028	PAC207
Creative Labs	WebCam Vista Pro		not working (no documentation)			(unknown)
Creative Labs	WebCam Vista Pro	Supplier	in progress	0x041e	0x4029	VC0301P
Cyber Snipa	Scout Webcam		works			(unknown)
Cyber Snipa	Spotter Webcam	Supplier	works			ZC0301P
D-Link	DRU 350C		in progress	0x06a5	0xd001	NW801
D-Link	DSB-C100 (Version a)		should work			CPiA
D-Link	DSB-C100 (Version b)		should work			OV511

D-Link	DSB-C110		works	0x0c45	0x600d	SN9C101
D-Link	DSB-C300 [clear case]		in progress	0x06a5	0xd001	NW802
D-Link	DSB-C310 (Rev B1)		works	0x05a9	0x8519	OV519
D-Link	DSC-350		works	0x084d	0x0003	SPCA500A
D-Link	DSC-350F		works	0x084d	0x0003	SPCA500A
D-Link	NetQam Pro 350 Plus		in progress	0x06a5	0xd001	NW801
DarkHorse	Infrared Night Vision USB PC Webcam + Mic PC1		not working (no information)	0x1b17	0x6111	(unknown high-speed
DBnawa	Rodin MPC-001 Computer Camera Dog		works	?	?	(unknown)
Dell	QuickCam OEM Notebook		in progress	0x046d	0x08c6	SPCA525A
Delux	Web Camera DLV-B32	Controller	depends (OEM)	0x0c45	0x6270	SN9C201
Dexxa	DexxaCam (with snapshot button)	Camera	partially works			STV602A
Dexxa	DexxaCam (without snapshot button)	Camera	partially works			STV600
Digicom	Galileo USB		works			CPiA
DigiLife	DDV-7000		not working (no documentation)	0x05e3	0x08ce	(unknown
Digital Dream	Epsilon 1.3		not working (no camera)	0x0733	0x1311	SPCA533A
Digital Dream	L'elegante		should work			STV680
Digital Dream	L'espion		works			STV680
Digital Dream	L'espion Xtra		not working (no documentation)			STV674
Digital Dream	L'esprit		works			STV680
Disney	Pix Micro Camera		in progress	0x2770	0x9050	SQ905C
Disney	Pix Micro Camera		in progress	0x2770	0x9050	SQ905C
ONT	CamStick		works			STV680
Dolphin Peripherals	007 Pocket Digital Camera		works			STV680
Dolphin Peripherals	PalmCAM Digital Camera		should work			STV680
Dolphin Peripherals	Pocket Digital Camera		should work			STV680
Dr. Hank	Webcam		in progress	0x0c45	0x608f	SN9C103
Dynalink	Digital Camera		works			CPiA
Easy Snap	Snake Eye		should work	0x093a	0x2468	PAC207
Elecom	UCAM-P1S30M	Controller	works	0x093a	0x26??	PAC7311
Ezonics	EZ Mega Cam (EZ-802)		not working (no camera)	0x1046	0x9967	W9967CF
Ezonics	EZ USB Cam II		should work			OV511+
Ezonics	EZCam		should work			CPiA
Ezonics	EZCam III		should work	0x04fc	0x0561	SPCA561
Ezonics	EZCam IV		should work	0x0c45	0x613c	SN9C120
Ezonics	EZCam Plus		not working (no documentation)			(unknown
Ezonics	EZCam Pro USB	Camera	in progress	0x052b	0xd001	NW801
Ezonics	iContact 2 (Pro II?)		works			(unknown
Ezonics	P10UC		not working (no information)			(unknown
Ezonics	PC CAM 10/USB		works			(unknown
Finet Technology	Palmpix DC-85	Manufacturer	not working (no camera)			SPCA500A
FlyCam	FlyCam USB100		should work	0x10fd	0x7e50	SPCA561

Fongkai	ChubbyCam	Camera	not working (no documentation)			(unknown)
Fongkai	PalmShot ADC350	Camera	not working (no documentation)			(unknown)
Fujifilm	Finepix 30i		not working (no documentation)			(unknown)
Fujifilm	Finepix 50i		not working (no documentation)			(unknown)
Fujifilm	FinePix 601i		not working (no documentation)			(unknown)
Fujifilm	FinePix E550		depends (UVC)	0x04cb	0x0172	(unknown)
Fujifilm	iX-1		should work			STV680
Gaba	CD10B4		should work			SQ905
GE	Easycam HO98063		works	0x0c45	0x600d	SN9C101
GE	EasyCam Pro HO98064		not working (no camera)	0x05a9	0xa518	OV518+
GE	EasyCam Pro HO98064		should work	0x05a9	0x?519	OV519
GE	GE MiniCam Pro HO98067 - 98756		not working (no camera)	0x0c45	0x60fe	SN9C105
geeks.com	USB Web Camera with Notebook Clip (Silver)		works	0x0c45	0x6019	SN9C101
Gemini Evolving Ideas	Gem 107 (1.3 Mega Pixel, USB PC Web Camera)	Controller	depends (OEM)	0x0c45	0x6270	SN9C201
Genius	e-Messenger 112		works	0x093a	0x2476	PAC207
Genius	Eye 110		works	0x093a	0x2472	PAC207
Genius	GE110 WebCam		should work	0x093a	0x2472	PAC207
Genius	Look 312P	Supplier	works	0x0ac8	0x301b	ZC0301P
Genius	Look 313 Media		not working (no documentation)	0x0458	0x7034	SN9C102P
Genius	Look 315FS		partially works	0x0c45	0x608f	SN9C103
Genius	Look 316	Supplier	works	0x0ac8	0x305b	ZC0305B
Genius	Messenger 310		not working (no documentation)	0x093a	0x2624	PAC7302
Genius	Slim 1322AF		not working (no information)			(unknown)
Genius	Slim 321C		not working (no documentation)	0x0458	0x7020	M5603C
Genius	VideoCam Express		should work			OV511+
Genius	VideoCam Express V2		should work	0x0458	0x7004	SPCA561A
Genius	VideoCam GE111		should work	0x093a	0x2471	PAC207
Genius	VideoCam GE112		should work	0x093a	0x2470	PAC207
Gigabyte	W566N laptop (built-in webcam)		depends (UVC)	0x064e	0xa111	UVC
Goldship	Webcam		works	0x093a	0x2468	PAC207
GoTec	Eye Cam 100		works	0x093a	0x2468	PAC207
GoTec	Visual Cam 100		works	0x093a	0x2468	PAC207
GoTec	Web Cam Robot 480	Supplier	in progress	0x0ac8	0x305b	VC0305
GoTec	Web Cão 480	Supplier	in progress	0x0ac8	0x305b	VC0305
GoTec	Web Robocão 480	Supplier	in progress	0x0ac8	0x305b	VC0305
GoTec	Web White Tiger 480	Supplier	in progress	0x0ac8	0x305b	VC0305
GPT	i-cam 340		works			(unknown)
Grandtec	V.cap		not working (no camera)			SPCA506A

GTW	SV 2107C (also sald by Shupying)		should work			SOODE
Electronics	SY-2107C (also sold by Shuoying)		should work			SQ905
Hama	Sightcam 100		should work			SPCA508A
Hawking Tech	DC120		should work			STV680
Hawking Tech			not working (no documentation)			(unknown)
Hawking Tech			should work			STV680
3	PD300		should work			OV511
Hawking Tech			should work			OV511+
Hawking Tech	UC310		should work			OV511
Hercules	Blog Webcam		in progress	0x06f8	0x3002	OV534
Hercules	Classic Link		in progress	0x06f8	0x3009	PAC7302
Hercules	Classic Silver	Controller	in progress	0x06f8	0x3004	SN9C105R
Hercules	Deluxe Optical Glass 1.3MP		works	0x06f8	0x3008	SN9C105
Hercules	Dualpix Chat and Show		not working (no information)			(unknown)
Hercules	Dualpix Exchange		depends (UVC)	0x06f8	0x3005	(unknown high-speed)
Hercules	Dualpix HD Webcam	Camera	in progress	0x06f8	0x3003	OV534
Hercules	stylish metallic webcam (1.3 Mpixels)		works	0x05a9	0x8519	OV530
Hercules	Webcam Classic		works			OV519
Hercules	Webcam Deluxe		works			OV519
Hitachi	iNC350		should work			STV680
Hithot	HH-301?	Supplier	should work	0x0ac8 ?	0x301b	ZC0301P
HP	1.3-Megapixel Webcam for Notebook PCs		not working (no information)			(unknown)
НР	2-Megapixel Autofocus Webcam		not working (no information)			(unknown)
HP	2-Megapixel Webcam		not working (no information)			(unknown)
HP	2MP Webcam		not working (no information)			(unknown)
HP	DV6000 Webcam (notebook built-in)		depends (UVC)	0x064e	0xa110	UVC
HP	DV9000 Webcam (notebook built-in)		depends (UVC)	0x0c45	0x62c0	UVC
HP	DV9000 Webcam (notebook built-in)		depends (UVC)	0x064e	0xa101	UVC
HP	DV9000 Webcam (notebook built-in)	Controller	not working (no camera)	0x05ca	0x1810	RY5U870
HP	DV9500t CTO Webcam (notebook built-in)		depends (UVC)	0x064e	0xa101	UVC
НР	USB 1.1 300K Pix (PG088AA) VGA Web Camera		not working (no information)			(unknown)
HP	VGA Webcam for Notebook PCs (Product# RD346AA)		not working (no documentation)	0x15b8	0x6002	(unknown high-speed)
НР	VGA Webcam with unique LCD clip		not working (no information)			(unknown)
НР	VGA Webcamera		not working (no information)			(unknown)
НР	Webcamera		not working (no information)			(unknown)
HY Technology	DC-N130t		should work			SQ905
I-View	NetView NV200M		should work			CPiA
I-View	NetView NV300M		should work			OV511
IBM	Net Camera (white)		not working (no documentation)			(unknown)

			not working (no			
IBM	Net Camera Pro (sage)		not working (no documentation)			(unknown)
IBM	PC Camera (beige)		not working (no camera)			XP-80807
IBM	PC Camera (black)		not working (no documentation)			(unknown)
IBM	PC Camera Pro (black)		not working (no documentation)			(unknown)
IBM	PC Camera Pro (white)		not working (no documentation)			(unknown)
IBM	PC Camera Pro Max (black)		not working (no documentation)			(unknown)
IBM	PC Camera Pro Max (white)		not working (no documentation)			(unknown)
iConcepts	Digital Camera (dual-mode)		should work			SQ905
IDT	IDT Digital Camera		should work			STV680
IDT	Kid's Digital Camera		should work			STV680
iMicro	Super Clear Webcam [CAM-IM210]		in progress	0x0c45	0x6128	SN9C110
Innovision	VisioCam		should work			STV680
Intel	CS110 Easy PC Camera		should work			SPCA508A
Intel	CS330 Create and Share		partially works	0x0733	0x0401	SPCA501A
Intel	CS331 Home PC Camera		in progress			SPCA501A
Intel	CS430 PC Camera Pro		works	0x0733	0x0430	SPCA505A
Intel	CS630 Pocket PC Camera		not working (no camera)			SPCA500A
Intel	Digital Movie Creator		not working (no camera)			SPCA551A
Intel	Me2Cam	Camera	should work			OV511+
Intel	Play Me2Cam		in progress			OV511+
Intel	Play QX3 Microscope	Camera	works			CPiA
IOMagic	MagicVision DR-CM200		should work			SPCA508A
IOMagic	MagicVision DR-CMUSB1		not working (no camera)			SPCA551A
iRez	Kritter 1.0	Camera	not working (no documentation)			NW801
iRez	Kritter 1.1		not working (no documentation)			(unknown)
iRez	Kritter 1.2		not working (no documentation)			(unknown)
iRez	USB Microscope		not working (no documentation)			(unknown)
Jenoptik	JDC 21 LCD		not working (no camera)	0x0733	0x2211	SPCA533A
Jenoptik	JDC 350		should work			SQ905
KB Gear	JamCam	Camera	not working (no documentation)			(unknown)
Kensington	VideoCam 67014		works	??	??	SE401
Kensington	VideoCam 67015		works			SE401
Kensington	VideoCam 67016		should work			SE401
Kensington	VideoCam 67017		should work			SE401
Kinstone	KS-1218	Supplier	works	0x0ac8	0x301b	ZC0301P
Kocom	KDC-100		should work			STV680
Kocom	KDC-110		should work			STV680
Kocom	KDC-120		should work			STV680
Kocom	KDC-130		should work			STV680

Kocom KMC-88 entire of common or common							
Kodak OVC323 and twerking (no documentation) OXC40a DXC40ba DXC40bb ADXC40bb	Kocom	KMC-88		-	0x0553	0x0100	STV672
Kodak DVC325 documentation bounds CASICPY (ASICPY)	Kocom	KMC-88i		. .			(unknown)
Kodick E7200 In progress 0x040a 0x0300 SPCA500A Konica e-mini Supplier should work 0x040d 0x08as 2702022 Labtec Webcam (B - Elch2) should work 0x040d 0x0929 SPCA561A Labtec Webcam (C) should work 0x040d 0x0929 SPCA561A Labtec webcam (aler models) camera works 0x040d 0x0929 SPCA561A Labtec webcam (later models) should work cunknown) cunknown Labtec WebCam - USB (model 961307-0403) decumentation works 0x093a 0x2464 PAC207 Labtec WebCam Plus decumentation works 0x093a 0x2464 PAC207 Labtec WebCam Plus camera works cunknown) cunknown Lego Lago Lago Cam camera works cunknown cunknown Lego Vision Command USB (like OulckCam Web) works cunknown cunknown	Kodak	DVC323		-	0x040a	0x0001	
Notebook Webcam	Kodak	DVC325		should work			SPCA501A
Labtec Notebook Webzarm (B - Elch2) Supplier works 0x046d 0x0929 SPCA561A Labtec Webzam (C) should work 0x046d 0x0929 SPCA561A Labtec webzam (early models) Camera works (unknown) Labtec webcam (later models) should work (unknown) Labtec webcam 1200 works 0x093a 0x246d PAC207 Labtec WebCam 1200 works 0x093a 0x246d PAC207 Labtec WebCam Plus works works (unknown) Labtec WebCam Plus works - (unknown) Lego Studios Camera works - (unknown) Lego Studios Camera works - 0v0780 Liferiek LT 9388 should work 0v0781 0v171 Liferiek LT 9388 should work 0v0711 0v171 0v171 Liferiek USB CapView should work 0v071 0v171	Kodak	EZ200		in progress	0x040a	0x0300	SPCA500A
Labtec Webcam (B - Elch2) should work 0x046d 0x0929 SPCAB61A Labtec Webcam (C) should work 0x046d 0x092b SPCAB61A Labtec webcam (early models) should work (unknown) Labtec WebCam - USB (model 961307-0403) doubt works 0x093b 0x2464 PAC207 Labtec WebCam 1200 works 0x093b 0x2464 PAC207 Labtec WebCam Plus doubt working (no doubt work of command the pack of c	Konica	e-mini		should work			STV680
Labtec Webcam (C) Camera works 0x046d 0x092b SPCA561A Labtec webcam (later models) should work (unknown) Labtec WebCam - USB (model 961307-0403) should work in old working (no documentation) 0x093a 0x2464 PAC207 Labtec WebCam 1200 works 0x093a 0x2464 PAC207 Labtec WebCam Plus not working (no documentation) (unknown) Labtec webcam pro works (unknown) Lego LegoCam Camera works (unknown) Lego Studios Camera works (unknown) Lego Vision Command USB (like QuickCam Web) works (unknown) Lego Vision Command USB (like QuickCam Web) works (unknown) Lego Vision Command USB (like QuickCam Web) works (unknown) Lego Studios Camera works (unknown) Lego USB Webcam (40Y8519) Supplier in progress 0x17ef 0x4802 VC0323 <	Labtec	Notebook Webcam	Supplier	works	0x046d	0x08aa	ZC0302
Labtec webcam (early models) Camera works (unknown) Labtec webcam (later models) should work (unknown) Labtec WebCam - USB (model 961307-0403) mot working (no documentation) 0x093a 0x2464 PAC207 Labtec WebCam Plus mot working (no documentation) 0x093a 0x2464 PAC207 Labtec WebCam Plus mot working (no documentation) 0x093a 0x2464 PAC207 Lego Lego Cam camera works (unknown) Lego Studios Camera works 0x17ef 0x4802 VC0323 Lego Vision Command USB (like QuickCam Web) works 0x17ef 0x4802 VC0323 Lifetek LT 9388 should work 0V511+ USB Capyliew should work 0V511+ Lifeview RoboCam works 0V511+ VC0323 VC0323 Lifeview RoboCam (WebCam (WebCam USB, con cavo partially works 0V511+ Lindy USB 2.0 WebCam (WebCam (WebCam USB, con cavo partially works <td>Labtec</td> <td>Webcam (B - Elch2)</td> <td></td> <td>should work</td> <td>0x046d</td> <td>0x0929</td> <td>SPCA561A</td>	Labtec	Webcam (B - Elch2)		should work	0x046d	0x0929	SPCA561A
Labtec	Labtec	Webcam (C)		should work	0x046d	0x092b	SPCA561A
Labtec	Labtec	webcam (early models)	Camera	works			(unknown)
Labtec Webcam 1200 works 0x093a 0x2464 PAC207 Labtec WebCam Plus not working (no documentation) Lego LegoCam Camera works STV610 Lego Studios Camera Works STV610 Lego Vision Command USB (like QuickCam Web) Lego Vision Command USB (like QuickCam Web) Lego Vision Command USB (like QuickCam Web) Lego Wish Command USB (like QuickCam Web) Lego Wish Command USB (like QuickCam Web) Lego Vision Command USB (like QuickCam Web) Lego Vision Command USB (like QuickCam Web) Lego Works Studios Camera Lego Vision Command USB (like QuickCam Web) Lifetek LT 938B Supplier in progress Ox17ef Ox4802 VC0323 Lifetek LT 938B Supplier Should work Ov4161 Lifetek USB CapView Should work Should work Ov4111 Lifetek USB CapView Should work Should work Ov4161 Logitech ClickSmart 310 Camera partially works Ov446d Ox0900 SPCA500A Logitech ClickSmart 510 Camera partially works Ov446d Ox0900 SPCA500A Logitech Color QuickCam 2 not working (no documentation) Logitech Color QuickCam 2 not working (no documentation) Logitech QuickCam (grayscale) not works Ov446d Ox092c SPCA561A Logitech QuickCam Communicate STX Supplier works Ox046d Ox0992 SPCA561A Logitech QuickCam Communicate STX Supplier works Ox046d Ox0992 VCC Logitech QuickCam Communicate STX Supplier works Ox046d Ox0894 ZC030x Logitech QuickCam Communicate STX Supplier works Ox046d Ox0894 ZC030x Logitech QuickCam Communicate STX Supplier works Ox046d Ox0897 SC030x Logitech QuickCam Communicate STX Supplier works Ox046d Ox0897 ZC030x Logitech QuickCam Communicate STX Supplier works Ox046d Ox0897 ZC030x Logitech QuickCam Communicate STX Supplier works Ox046d Ox0897 ZC030x Logitech QuickCam Communicate STX Supplier works Ox046d Ox0897 ZC030x Logitech QuickCam Communicate STX Supplier works Ox046d Ox0897 ZC030x Logitech QuickCam Communic	Labtec	webcam (later models)		should work			(unknown)
Labtec WebCam Plus documentation) Labtec webcam pro	Labtec	WebCam - USB (model 961307-0403)					(unknown)
Labtec WebCam PIUS	Labtec	Webcam 1200		works	0x093a	0x2464	PAC207
Lego Studios Camera works (unknown) Lego Vision Command USB (like QuickCam Web) Lenovo USB Webcam (4078519) Supplier in progress 0x17ef 0x4802 VC0323 Lifetek LT 9388 should work vorks OV511+ Lifeview RoboCam works OV511+ Lifeview USB CapView should work vorks OV511+ Lindy TC-300 Camera partially works OV511+ Lindy TC-300 Camera partially works OV511+ Lindy USB 2.0 WebCam (WebCam USB, con cavo 1.5m) and working (no documentation) Logitech ClickSmart 310 works 0x046d 0x0900 SPCA500A Logitech Color QuickCam Oxford Oxf	Labtec	WebCam Plus		3 ((unknown)
Lego Vision Command USB (like QuickCam Web) works (unknown) Lenovo USB Webcam (40Y8519) Supplier in progress 0x17ef 0x4802 VC0323 Lifetek LT 9388 should work OV511+ Lifeview RoboCam works OV511+ Lifeview USB CapView should work OV511+ Lindy TC-300 Camera partially works OV511+ Lindy USB 2.0 WebCam (WebCam USB, con cavo Information) Logitech ClickSmart 310 works OX046d 0x0900 SPCA500A Logitech Color QuickCam Ox000 Camera not working (no documentation) Logitech Color QuickCam Ox000 Camera not working (no documentation) Logitech Color QuickCam Camera not working (no documentation) Logitech Color QuickCam Camera not working (no documentation) Logitech Color QuickCam Camera not working (no documentation) Logitech QuickCam Communicate STX Supplier works NotAdd Ox092c SPCA561A Logitech QuickCam Communicate STX Supplier works NotAdd Ox088ad ZC0302c Logitech QuickCam Communicate STX Supplier works NotAdd Ox088ad ZC030x Logitech QuickCam Cool Supplier works NotAdd Ox088ad ZC030x Logitech QuickCam Cool Supplier works NotAdd Ox088ad ZC030x Logitech QuickCam Cool Supplier works NotAdd Ox086d NotAdd Ox086d CulkCam Communicate STX Logitech QuickCam Cool Supplier works NotAdd Ox086d NotAdd	Labtec	webcam pro		works			(unknown)
Lego Vision Command USB (like QuickCam Web) Lenovo USB Webcam (40Y8519) Liffetek LT 9388 Liffetek LT 9388 Liffetek RoboCam Liffeview RoboCam USB CapView USB CapView USB CapView Lindy Liffeyiew USB 2.0 WebCam (WebCam USB, con cavo 1.5m) Logitech CilckSmart 310 Logitech CilckSmart 510 Logitech Color QuickCam Logitech QuickCam (grayscale) Logitech QuickCam Chat (B) Logitech QuickCam Communicate Logitech QuickCam Communicate Logitech QuickCam Communicate STX Logitech QuickCam Communicate STX Supplier Should work Sho	Lego	LegoCam	Camera	works			STV610
Lenovo	Lego	Studios Camera		works			(unknown)
Lifetekk LT 9388 should work works OV511+ Lifeview RoboCam works OV511 Lifeview USB CapView should work OV511+ Lindy TC-300 Camera partially works OV511+ Lindy TS-300 WebCam (WebCam USB, con cavo 1.5m) Logitech ClickSmart 310 works Ox046d Ox0900 SPCA500A Logitech ClickSmart 510 not working (no documentation) Logitech Color QuickCam not working (no documentation) Logitech Color QuickCam 2 not working (no documentation) Logitech QuickCam (grayscale) not working (no documentation) Logitech QuickCam (grayscale) not working (no documentation) Logitech QuickCam (grayscale) not working (no documentation) Logitech QuickCam (hat works Ox046d Ox092c SPCA561A Logitech QuickCam Chat works Ox046d Ox092c SPCA561A Logitech QuickCam Clip not working (no documentation) Logitech QuickCam Communicate STX Supplier works Ox046d Ox08f5 Unknown) Logitech QuickCam Communicate STX Supplier works Ox046d Ox0887 VCO302 Logitech QuickCam Communicate STX Supplier works Ox046d Ox0887 ZCO302 Logitech QuickCam Communicate STX Supplier works Ox046d Ox0887 ZCO302 Logitech QuickCam Connect Supplier should work Ox046d Ox0887 ZCO30x Logitech QuickCam Cool Supplier should work Ox046d Ox0887 ZCO30x Logitech QuickCam Cool Supplier works Ox046d Ox0887 ZCO30x Logitech QuickCam Cool Supplier should work Ox046d Ox0887 ZCO30x Logitech QuickCam Cool Supplier works Ox046d Ox0887 ZCO30x Logitech QuickCam Cool Supplier should work Ox046d Ox0887 ZCO30x Logitech QuickCam Cool Supplier works Ox046d Ox0887 ZCO30x Logitech QuickCam Cool Supplier should work Ox046d Ox0886 ZCO30x Logitech QuickCam Cool Supplier works Ox046d Ox0886 ZCO30x Logitech QuickCam Cool Ox06cm Supplier should work Ox046d Ox0886 ZCO30x Logitech QuickCam Cool Ox06cm Supplier should work Ox046d Ox0886 ZCO30x Logitech QuickCam Cool Ox06cm Supplier should work Ox046d Ox0886 ZCO30x Logitech QuickCam Deluxe for Notebooks	Lego	Vision Command USB (like QuickCam Web)		works			(unknown)
Lifeview USB CapView Should work OV511+ Lindy TC-300 Camera partially works OV511+ Lindy TC-300 Camera partially works OV511+ Lindy USB 2.0 WebCam (WebCam USB, con cavo 1.5m) not working (no information) Logitech ClickSmart 310 works Ox046d Ox0900 SPCA500A Logitech ClickSmart 510 not working (no documentation) Logitech Color QuickCam not working (no documentation) Logitech Color QuickCam not working (no documentation) Logitech Color QuickCam not working (no documentation) Logitech QuickCam (grayscale) not working (no documentation) Logitech QuickCam (grayscale) not working (no documentation) Logitech QuickCam Chat works Ox046d Ox092c SPCA561A Logitech QuickCam Chat works Ox046d Ox092c SPCA561A Logitech QuickCam Clip not working (no documentation) Logitech QuickCam Clip not working (no documentation) Logitech QuickCam Communicate Logitech QuickCam Communicate works Ox046d Ox092c UVC Logitech QuickCam Communicate Works Ox046d Ox0845 (unknown) Logitech QuickCam Communicate STX Supplier works Ox046d Ox0847 VC0302 Logitech QuickCam Communicate STX Supplier works Ox046d Ox0847 VC0302 Logitech QuickCam Communicate STX Supplier works Ox046d Ox0847 VC0302 Logitech QuickCam Communicate STX Supplier works Ox046d Ox0847 VC0302 Logitech QuickCam Connect Supplier should work Ox046d Ox0847 ZC030x Logitech QuickCam Cool Supplier works Ox046d Ox0846 ZC030x Logitech QuickCam Cool Ox046d Ox0846	Lenovo	USB Webcam (40Y8519)	Supplier	in progress	0x17ef	0x4802	VC0323
Lifeview USB CapView Should work OV511+ Lindy TC-300 Camera partially works OV511+ Lindy USB 2.0 WebCam (WebCam USB, con cavo 1.5m) Logitech ClickSmart 310 works Ox046d Ox0900 SPCA500A Logitech Color QuickCam Odcumentation) Logitech Color QuickCam Odcumentation Logitech QuickCam Chat Works Ox046d Ox092c SPCA561A Logitech QuickCam Chat Works Ox046d Ox092c SPCA561A Logitech QuickCam Clip Odcumentation Logitech QuickCam Communicate Odcumentation Logitech QuickCam Communicate Deluxe Odcumentation Logitech QuickCam Communicate STX Supplier Works Ox046d Ox0845 UVCO Logitech QuickCam Communicate STX Supplier Works Ox046d Ox0847 VC0302 Logitech QuickCam Communicate STX Supplier Works Ox046d Ox0847 VC0302 Logitech QuickCam Communicate STX Supplier Works Ox046d Ox0847 VC0302 Logitech QuickCam Communicate STX Supplier Works Ox046d Ox0847 VC0302 Logitech QuickCam Connect Supplier Should work Ox046d Ox0847 ZC030x Logitech QuickCam Cool Supplier Works Ox046d Ox0847 ZC030x Logitech QuickCam Cool Supplier Should work Ox046d Ox0847 ZC030x Logitech QuickCam Cool Supplier Should work Ox046d Ox0847 ZC030x Logitech QuickCam Cool Supplier Should work Ox046d Ox0847 ZC030x Logitech QuickCam Cool Supplier Should work Ox046d Ox0847 ZC030x Logitech QuickCam Cool Supplier Should work Ox046d Ox0847 ZC030x Logitech QuickCam Cool Supplier Should work Ox046d Ox0847 ZC030x Logitech QuickCam Deluxe for Notebooks depends (UVC) Ox046d Ox0846 ZC030x Logitech QuickCam Deluxe for Notebooks depends (UVC) Ox046d Ox0846 ZC030x Logitech QuickCam Deluxe for Notebooks	Lifetek	LT 9388		should work			OV511+
Lindy TC-300 Camera partially works	Lifeview	RoboCam		works			OV511
Lindy 1.5m) Logitech ClickSmart 310	Lifeview	USB CapView		should work			OV511+
Logitech ClickSmart 310 works 0x046d 0x0900 SPCA500A Logitech ClickSmart 510 not working (no documentation) Logitech Color QuickCam not working (no documentation) Logitech Color QuickCam 2 not working (no documentation) Logitech QuickCam (grayscale) not working (no documentation) Logitech QuickCam (grayscale) not working (no documentation) Logitech QuickCam Chat works 0x046d 0x092e SPCA561A Logitech QuickCam Chat works 0x046d 0x092e SPCA561A Logitech QuickCam Clip not working (no documentation) Logitech QuickCam Clip not working (no documentation) Logitech QuickCam Clip not working (no documentation) Logitech QuickCam Communicate SPX Supplier works 0x046d 0x092e UVC Logitech QuickCam Communicate STX Supplier works 0x046d 0x084d 0x092e UVC Logitech QuickCam Communicate STX Supplier works 0x046d 0x084d 0x092e SPCA527A Logitech QuickCam Communicate STX Supplier works 0x046d 0x084d 0x092e SPCA527A Logitech QuickCam Communicate STX Supplier works 0x046d 0x084d 0x0992 SPCA527A Logitech QuickCam Communicate STX Supplier works 0x046d 0x084d 0	Lindy	TC-300	Camera	partially works			OV511+
Logitech ClickSmart 510 not working (no documentation) Logitech Color QuickCam not working (no documentation) Logitech Color QuickCam 2 not working (no documentation) Logitech QuickCam (grayscale) not working (no documentation) Logitech QuickCam (grayscale) not working (no documentation) Logitech QuickCam Chat works 0x046d 0x092e SPCA561A Logitech QuickCam Chat works 0x046d 0x092e SPCA561A Logitech QuickCam Clip not working (no documentation) Logitech QuickCam Clip not working (no documentation) Logitech QuickCam Clip not working (no documentation) Logitech QuickCam Communicate Logitech QuickCam Communicate STX Supplier works 0x046d 0x08f5 (unknown) Logitech QuickCam Communicate STX Supplier works 0x046d 0x08ad ZC0302 Logitech QuickCam Communicate STX Supplier works 0x046d 0x08d7 VC0302 Logitech QuickCam Communicate STX Supplier works 0x046d 0x08d7 VC0302 Logitech QuickCam Connect Supplier should work 0x046d 0x08d9 ZC030x Logitech QuickCam Cool Supplier works 0x046d 0x08d7 ZC030x Logitech QuickCam Cool Supplier works 0x046d 0x08d7 ZC030x Logitech QuickCam Cool Supplier works 0x046d 0x08d7 ZC030x Logitech QuickCam Cool Supplier should work 0x046d 0x08d7 ZC030x Logitech QuickCam Deluxe for Notebooks depends (UVC) 0x046d 0x08d7 ZC030x Logitech QuickCam Deluxe for Notebooks	Lindy	· · · · · · · · · · · · · · · · · · ·		. .	?	?	(unknown)
Logitech Color QuickCam (unknown) Logitech Color QuickCam 2 not working (no documentation) (unknown) Logitech Color QuickCam 2 not working (no documentation) (unknown) Logitech QuickCam (grayscale) not working (no documentation) (unknown) Logitech QuickCam (grayscale) not working (no documentation) (unknown) Logitech QuickCam Chat works 0x046d 0x092c SPCA561A Logitech QuickCam Chat works 0x046d 0x092c SPCA561A Logitech QuickCam Clip not working (no documentation) (unknown) Logitech QuickCam Communicate should work 0x046d 0x092c SPCA561A Logitech QuickCam Communicate deluxe depends (UVC) 0x046d 0x092c UVC Logitech QuickCam Communicate STX Supplier works 0x046d 0x089d ZC0302 Logitech QuickCam Communicate STX Supplier works 0x046d 0x08d7 VC0302 Logitech QuickCam Communicate STX Supplier works 0x046d 0x089d ZC030x Logitech QuickCam Connect Supplier should work 0x046d 0x08d9 ZC030x Logitech QuickCam Cool Supplier works 0x046d 0x08af ZC030x Logitech QuickCam Cool Supplier should work 0x046d 0x08af ZC030x Logitech QuickCam Cool Supplier should work 0x046d 0x08ac ZC030x Logitech QuickCam Cool Supplier should work 0x046d 0x08ac ZC030x Logitech QuickCam Cool Supplier should work 0x046d 0x08ac ZC030x Logitech QuickCam Deluxe for Notebooks	Logitech	ClickSmart 310		works	0x046d	0x0900	SPCA500A
Logitech Color QuickCam 2 documentation) Logitech Color QuickCam 2 not working (no documentation) Logitech QuickCam (grayscale) Logitech QuickCam Chat works 0x046d 0x092e SPCA561A Logitech QuickCam Chat (B) Logitech QuickCam Clip not working (no documentation) Logitech QuickCam Clip not working (no documentation) Logitech QuickCam Communicate Logitech QuickCam Communicate Deluxe depends (UVC) 0x046d 0x092e SPCA561A Logitech QuickCam Communicate STX Supplier works 0x046d 0x08f5 (unknown) Logitech QuickCam Communicate STX Supplier works 0x046d 0x08d7 VC0302 Logitech QuickCam Communicate STX Supplier works 0x046d 0x08d7 VC0302 Logitech QuickCam Communicate STX Supplier works 0x046d 0x08d7 VC0302 Logitech QuickCam Communicate STX Supplier works 0x046d 0x08d9 ZC030x Logitech QuickCam Connect Supplier should work 0x046d 0x08d7 ZC030x Logitech QuickCam Cool Supplier works 0x046d 0x08d7 ZC030x Logitech QuickCam Cool Supplier should work 0x046d 0x08d7 ZC030x Logitech QuickCam Cool Supplier should work 0x046d 0x08af ZC030x Logitech QuickCam Cool Supplier should work 0x046d 0x08ac ZC030x Logitech QuickCam Deluxe for Notebooks	Logitech	ClickSmart 510		. .			(unknown)
Logitech QuickCam (grayscale) Logitech QuickCam (grayscale) Logitech QuickCam Chat Logitech QuickCam Chat Morks Ox046d Ox092e SPCA561A Logitech QuickCam Chat (B) Morks Ox046d Ox092c SPCA561A Logitech QuickCam Clip Mocumentation) Logitech QuickCam Clip Logitech QuickCam Communicate Should work Ox046d Ox08f5 (unknown) Logitech QuickCam Communicate Deluxe Logitech QuickCam Communicate STX Supplier Works Ox046d Ox08d7 VC0302 Logitech QuickCam Communicate STX Supplier Works Ox046d Ox08d7 VC0302 Logitech QuickCam Communicate STX Supplier Works Ox046d Ox08d7 VC0302 Logitech QuickCam Communicate STX Supplier Works Ox046d Ox08d7 VC0302 Logitech QuickCam Communicate STX Supplier Works Ox046d Ox08d7 VC0302 Logitech QuickCam Connect Supplier Should work Ox046d Ox08d9 ZC030x Logitech QuickCam Cool Supplier Works Ox046d Ox08d7 ZC030x Logitech QuickCam Cool Supplier Should work Ox046d Ox08d7 ZC030x Logitech QuickCam Cool Supplier Should work Ox046d Ox08d7 ZC030x Logitech QuickCam Cool Supplier Should work Ox046d Ox08ac ZC030x Logitech QuickCam Deluxe for Notebooks depends (UVC) Ox046d Ox09c1 (unknown high-speed)	Logitech	Color QuickCam		3 .			(unknown)
Logitech QuickCam (grayscale) Logitech QuickCam Chat Logitech QuickCam Chat Logitech QuickCam Chat (B) Logitech QuickCam Clip Cogitech QuickCam Clip Cogitech QuickCam Communicate Logitech QuickCam Communicate Logitech QuickCam Communicate Deluxe Logitech QuickCam Communicate STX Supplier works 0x046d 0x0845 (unknown) Logitech QuickCam Communicate STX Supplier works 0x046d 0x08992 UVC Logitech QuickCam Communicate STX Supplier works 0x046d 0x08ad ZC0302 Logitech QuickCam Communicate STX Supplier works 0x046d 0x08d7 VC0302 Logitech QuickCam Communicate STX Supplier works 0x046d 0x08d7 VC0302 Logitech QuickCam Connect Supplier should work 0x046d 0x08d9 ZC030x Logitech QuickCam Cool Supplier works 0x046d 0x08d9 ZC030x Logitech QuickCam Cool Supplier should work 0x046d 0x08ac ZC030x Logitech QuickCam Cool Supplier should work 0x046d 0x08ac ZC030x Logitech QuickCam Cool Supplier should work 0x046d 0x09c1 (unknown high-speed)	Logitech	Color QuickCam 2		-			(unknown)
Logitech QuickCam Chat (B) Logitech QuickCam Clip Couling Communicate Logitech QuickCam Communicate Logitech QuickCam Communicate Logitech QuickCam Communicate Deluxe Logitech QuickCam Communicate STX Supplier works Ox046d Ox08dd Ox0992 UVC Logitech QuickCam Communicate STX Supplier works Ox046d Ox08dd ZC0302 Logitech QuickCam Communicate STX Supplier works Ox046d Ox08d7 VC0302 Logitech QuickCam Communicate STX Supplier works Ox046d Ox08d7 VC0302 Logitech QuickCam Communicate STX Supplier works Ox046d Ox0992 SPCA527A Logitech QuickCam Connect Supplier should work Ox046d Ox08d9 ZC030x Logitech QuickCam Cool Supplier works Ox046d Ox08df ZC030x Logitech QuickCam Cool Supplier should work Ox046d Ox08ac ZC030x Logitech QuickCam Cool Supplier should work Ox046d Ox08ac ZC030x Logitech QuickCam Cool Supplier should work Ox046d Ox08ac ZC030x Logitech QuickCam Deluxe for Notebooks depends (UVC) Ox046d Ox09c1 (unknown high-speed)	Logitech	QuickCam (grayscale)		. .			(unknown)
Logitech QuickCam Clip not working (no documentation) (unknown) Logitech QuickCam Communicate should work ox046d ox08f5 (unknown) Logitech QuickCam Communicate Deluxe depends (UVC) ox046d ox0992 UVC Logitech QuickCam Communicate STX Supplier works ox046d ox08ad ZC0302 Logitech QuickCam Communicate STX Supplier works ox046d ox08d7 VC0302 Logitech QuickCam Communicate STX depends (UVC) ox046d ox0992 SPCA527A Logitech QuickCam Connect Supplier should work ox046d ox08d9 ZC030x Logitech QuickCam Cool Supplier works ox046d ox08d7 ZC030x Logitech QuickCam Cool Supplier works ox046d ox08af ZC030x Logitech QuickCam Cool Supplier should work ox046d ox08ac ZC030x Logitech QuickCam Cool Supplier should work ox046d ox08ac ZC030x Logitech QuickCam Deluxe for Notebooks depends (UVC) ox046d ox09c1 (unknown high-speed)	Logitech	QuickCam Chat		works	0x046d	0x092e	SPCA561A
Logitech QuickCam Communicate should work ox046d ox08f5 (unknown) Logitech QuickCam Communicate Deluxe depends (UVC) ox046d ox0992 UVC Logitech QuickCam Communicate STX Supplier works ox046d ox08dd ZC0302 Logitech QuickCam Communicate STX Supplier works ox046d ox08dd VC0302 Logitech QuickCam Communicate STX Supplier works ox046d ox08dd VC0302 Logitech QuickCam Communicate STX depends (UVC) ox046d ox0992 SPCA527A Logitech QuickCam Connect Supplier should work ox046d ox08dd ZC030x Logitech QuickCam Cool Supplier works ox046d ox08dd ZC030x Logitech QuickCam Cool Supplier works ox046d ox08af ZC030x Logitech QuickCam Cool Supplier should work ox046d ox08ac ZC030x Logitech QuickCam Deluxe for Notebooks depends (UVC) ox046d ox09c1 (unknown high-speed)	Logitech	Quickcam Chat (B)		works	0x046d	0x092c	SPCA561A
Logitech QuickCam Communicate Deluxe Logitech QuickCam Communicate STX Supplier works 0x046d 0x0992 Logitech QuickCam Communicate STX Supplier works 0x046d 0x08ad ZC0302 Logitech QuickCam Communicate STX Supplier works 0x046d 0x08d7 VC0302 Logitech QuickCam Communicate STX Supplier works 0x046d 0x0992 SPCA527A Logitech QuickCam Connect Supplier should work 0x046d 0x08d9 ZC030x Logitech QuickCam Cool Supplier works 0x046d 0x08af ZC030x Logitech QuickCam Cool Supplier should work 0x046d 0x08ac ZC030x Logitech QuickCam Cool Supplier should work 0x046d 0x08ac ZC030x Logitech QuickCam Deluxe for Notebooks depends (UVC) 0x046d 0x08ac ZC030x (unknown high-speed)	Logitech	QuickCam Clip		. .			(unknown)
LogitechQuickCam Communicate STXSupplierworks0x046d0x08adZC0302LogitechQuickCam Communicate STXSupplierworks0x046d0x08d7VC0302LogitechQuickCam Communicate STXdepends (UVC)0x046d0x0992SPCA527ALogitechQuickCam ConnectSuppliershould work0x046d0x08d9ZC030xLogitechQuickCam CoolSupplierworks0x046d0x08afZC030xLogitechQuickCam CoolSuppliershould work0x046d0x08acZC030xLogitechQuickCam Deluxe for Notebooksdepends (UVC)0x046d0x09c1(unknown high-speed)	Logitech	QuickCam Communicate		should work	0x046d	0x08f5	(unknown)
Logitech QuickCam Communicate STX Supplier works 0x046d 0x08d7 VC0302 Logitech QuickCam Communicate STX depends (UVC) 0x046d 0x0992 SPCA527A Logitech QuickCam Connect Supplier should work 0x046d 0x08d9 ZC030x Logitech QuickCam Cool Supplier works 0x046d 0x08af ZC030x Logitech QuickCam Cool Supplier should work 0x046d 0x08ac ZC030x Logitech QuickCam Cool Supplier should work 0x046d 0x08ac ZC030x Logitech QuickCam Deluxe for Notebooks depends (UVC) 0x046d 0x09c1 (unknown high-speed)	Logitech	QuickCam Communicate Deluxe		depends (UVC)	0x046d	0x0992	UVC
LogitechQuickCam Communicate STXdepends (UVC)0x046d0x0992SPCA527ALogitechQuickCam ConnectSuppliershould work0x046d0x08d9ZC030xLogitechQuickCam CoolSupplierworks0x046d0x08afZC030xLogitechQuickCam CoolSuppliershould work0x046d0x08acZC030xLogitechQuickCam Deluxe for Notebooksdepends (UVC)0x046d0x09c1(unknown high-speed)	Logitech	QuickCam Communicate STX	Supplier	works	0x046d	0x08ad	ZC0302
LogitechQuickCam ConnectSuppliershould work0x046d0x08d9ZC030xLogitechQuickCam CoolSupplierworks0x046d0x08afZC030xLogitechQuickCam CoolSuppliershould work0x046d0x08acZC030xLogitechQuickCam Deluxe for Notebooksdepends (UVC)0x046d0x09c1(unknown high-speed)	Logitech	QuickCam Communicate STX	Supplier	works	0x046d	0x08d7	VC0302
Logitech QuickCam Cool Supplier works 0x046d 0x08af ZC030x Logitech QuickCam Cool Supplier should work 0x046d 0x08ac ZC030x Logitech QuickCam Deluxe for Notebooks depends (UVC) 0x046d 0x09c1 (unknown high-speed)	Logitech	QuickCam Communicate STX		depends (UVC)	0x046d	0x0992	SPCA527A
Logitech QuickCam Cool Supplier should work 0x046d 0x08ac ZC030x Logitech QuickCam Deluxe for Notebooks depends (UVC) 0x046d 0x09c1 (unknown high-speed)	Logitech	QuickCam Connect	Supplier	should work	0x046d	0x08d9	ZC030x
Logitech QuickCam Deluxe for Notebooks depends (UVC) 0x046d 0x09c1 (unknown high-speed)	Logitech	QuickCam Cool	Supplier	works	0x046d	0x08af	ZC030x
Logitech QuickCam Deluxe for Notebooks depends (UVC) 0x046d 0x09c1 high-speed)	Logitech	QuickCam Cool	Supplier	should work	0x046d	0x08ac	ZC030x
Logitech QuickCam E1000 Supplier works 0x046d 0x08af ZC030x	Logitech	QuickCam Deluxe for Notebooks		depends (UVC)	0x046d	0x09c1	•
	Logitech	QuickCam E1000	Supplier	works	0x046d	0x08af	ZC030x

Logitech	QuickCam E2500	Supplier	works	0x046d	0x089d	ZC030x
Logitech	QuickCam Express		in progress	0x046d	0xd001	NW801
Logitech	Quickcam Express (D - Elch2)		should work	0x046d	0x0928	SPCA561A
Logitech	QuickCam Express (with snapshot button)	Camera	partially works			STV602A
Logitech	QuickCam Express (without snapshot button)		in progress			STV600
Logitech	QuickCam for Notebooks (A - square?)		should work	0x046d	0x092a	SPCA561A
Logitech	QuickCam for Notebooks (rounded)	Camera	should work			ZC0302
Logitech	QuickCam for Notebooks (yet another!)	Supplier	works	0x046d	0x08dd	ZC030x
Logitech	QuickCam for Notebooks Deluxe (A)	Supplier	works	0x046d	0x08a9	ZC0302
Logitech	QuickCam for Notebooks Deluxe (B)	Supplier	should work	0x046d	0x08d8	VC0302
Logitech	QuickCam for Notebooks Deluxe (M/N: V-UBG35)	Supplier	in progress	0x046d	0x08a8	ZC0302
Logitech	QuickCam for Notebooks Pro (new - 2006)		depends (UVC)	0x046d	0x08cb	SPCA525A
Logitech	QuickCam for Notebooks Pro (old)		in progress	0x046d	0x08c3	SPCA525A
Logitech	QuickCam Fusion (new - 2006)		depends (UVC)	0x046d	0x08ca	SPCA525A
Logitech	QuickCam Fusion (old)		in progress	0x046d	0x08c1	SPCA525A
Logitech	QuickCam Fusion Ultra		depends (UVC)			(unknown)
Logitech	QuickCam Home	Controller	not working (no documentation)	0x046d	0x0801	STV610
Logitech	QuickCam Messenger	Camera	works	0x046d	0x08f0	(unknown)
Logitech	QuickCam Messenger	Supplier	in progress	0x046d	0x08da	ZC030x
Logitech	QuickCam Messenger (plus or new)		should work	0x046d	0x08f6	(unknown)
Logitech	QuickCam Notebooks Pro		should work			(unknown)
Logitech	QuickCam OEM Cisco VT Camera II		in progress	0x046d	0x08c7	SPCA525A
Logitech	Quickcam OEM Dell Notebook		in progress	0x046d	0x08c6	SPCA525A
Logitech	QuickCam Orbit/Sphere	Camera	works			SAA8116HL
Logitech	QuickCam Orbit/Sphere AF		depends (UVC)	0x046d	0x0994	UVC
Logitech	QuickCam Orbit/Sphere MP (new - 2006)		depends (UVC)	0x046d	0x08cc	SPCA525A
Logitech	QuickCam Orbit/Sphere MP (old)		in progress	0x046d	0x08c2	SPCA525A
Logitech	QuickCam Pro (beige focus ring)	Controller	works	0x046d	0x0810	USS-720
Logitech	QuickCam Pro (dark focus ring)	Camera	works	0x046d	0xd001	NW801
Logitech	QuickCam Pro 3000	Controller	works			SAA8116HL
Logitech	QuickCam Pro 4000	Camera	works (OEM)			SAA8116HL
Logitech	QuickCam Pro 5000 (new - 2006)		depends (UVC)	0x046d	0x08ce	SPCA525A
Logitech	QuickCam Pro 5000 (old)		in progress	0x046d	0x08c5	SPCA525A
Logitech	QuickCam Pro 9000 [QCAM-200S]		depends (UVC)	0x046d	0x0990	SPCA527A
Logitech	QuickCam Pro for Notebooks	Controller	works	0x046d	0x08b1	SAA8116HL
Logitech	QuickCam Pro for Notebooks [QCAM-200V] (2007)		depends (UVC)	0x046d	0x0991	(unknown)
Logitech	QuickCam Traveler		not working (no documentation)			(unknown)
Logitech	QuickCam Ultra Vision		depends (UVC)	0x046d	0x08c9	SPCA525A
Logitech	QuickCam VC	Camera	in progress			USS-720
Logitech	QuickCam Web	Controller	not working (no camera)	0x046d	0x0801	STV610
Logitech	QuickCam Web (round)	Camera	partially works			STV610
Logitech	QuickCam Web (square)		not working (no documentation)			(unknown)
Logitech	QuickCam Zoom (new version - silver)	Controller	should work	0x046d	0x08b4	SAA8116HL
Logitech	QuickCam Zoom (old version)	Camera	should work			(unknown)
Macally	IceCam		in progress	0x0c45	0x6005	SN9C101

MagicVision	DR-CMUSB1		in progress	0x0573	0×0003	NT1003
MagicVision	DRCM200		in progress partially works	0.0373	0x0003	SPCA508A
Magpix	B350 Binocular Camera		should work			SQ905
Maitech	AWK-300		should work			OV511+
Maxell	Compact PC PM3		should work	0x060b	0xa001	SPCA561A
Maxell	Maxcam (MPCC-1)		should work			OV511
Maxxtro	CAM22U		should work			OV511
Maxxtro	CAM31U		works			(unknown)
Meade	MicrOcular		works	0x093a	0x2468	PAC207
Meade	MicrOcular 1.3 MP		not working (no documentation)	0x0e96	0xc001	(unknown)
MediaForte	MV300		should work			OV511
MediaForte	PC Vision 300		should work			OV511
Medion	MD9388		should work			OV511+
Micro	Flexicam IC70C	Manufacturer	not working (no			(unknown)
Innovations Micro	Tickleam 10700	Warraractarer	documentation) not working (no			(driknown)
Innovations	IC300C	Manufacturer	documentation)			(unknown)
Micro Innovations	iCAM100 (IC170C)	Manufacturer	not working (no documentation)			(unknown)
Micro Innovations	Micro TravelCam Plus	Manufacturer	not working (no documentation)			(unknown)
Micro Innovations	Micro TravelCam Pro	Manufacturer	not working (no documentation)			(unknown)
Micro Innovations	Webcam Basic IC50C	Manufacturer	works	0x04fc	0x0561	SPCA561A
Micro Innovations	Webcam IC100C	Manufacturer	not working (no documentation)			(unknown)
Micro Innovations	Webcam IC150C	Manufacturer	not working (no documentation)			(unknown)
Micro Innovations	Webcam IC435C	Manufacturer	works	0x093a	0x2468	PAC207
Micro Innovations	Webcam Matrix IC445C	Manufacturer	should work	0x0c45	0x60af	SN9C103
Micro Innovations	Webcam Mobile IC400C	Manufacturer	in progress			SPCA508A
Micro Innovations	Webcam Plus IC200C	Manufacturer	works	0x0461?	0x0815?	SPCA508A
Microsoft	LifeCam NX-3000		depends (UVC)	0x045e	0x0721	(unknown high-speed)
Microsoft	LifeCam NX-6000		depends (UVC)	0x045e	0x00f8	UVC
Microsoft	LifeCam VX-1000	Controller	should work	0x045e	0x00f7	SN9C105R
Microsoft	LifeCam VX-3000	Controller	works	0x045e	0x00f5	SN9C105R
Microsoft	LifeCam VX-5000		depends (UVC)	0x045e	??	(unknown high-speed)
Microsoft	LifeCam VX-6000	Controller	in progress	0x045e	0x00f4	SN9C202
Microsoft	LifeCam VX-7000		depends (UVC)	0x045e	0x0723	UVC
Microsoft	Xbox Live Vision (Xbox 360)		depends (UVC)	0x045e	0x0294	(unknown)
Microsoft	Xbox Video Chat (original Xbox)		should work	0x045e	0x028c	OV530
Microtek	EyeStar		should work			CPiA
Microtek	MN-100		should work			STV680
Microtek	MN-350		should work			STV680
Microtek	Take-it 350		should work			STV680
Mikomi (Ming Jong)	M6210 Desktop PC Cam		not working (no information)			(unknown)

Mikomi (Ming Jong)	M6211 Interactive Sketch Cam	not working (no information)			(unknown)
Mikomi (Ming Jong)	M6215 Desktop PC Cam	not working (no information)			(unknown)
Mikomi (Ming Jong)	M6215 Desktop PC Cam	not working (no information)			(unknown)
Mikomi (Ming Jong)	M6215 Desktop PC Cam	not working (no information)			(unknown)
Mikomi (Ming Jong)	M6216M Web Cam with microphone	not working (no information)			(unknown)
Mikomi (Ming Jong)	M6217 Desktop PC Cam	in progress	0x0c45	0x608f	SN9C103
Mikomi (Ming Jong)	M6217M Desktop PC Cam with microphone	not working (no information)			SN9C103
Mikomi (Ming Jong)	M6218 Desktop PC Cam	not working (no information)			(unknown)
Mikomi (Ming Jong)	M6218M Desktop PC Cam with microphone	not working (no information)			SN9C103
Mikomi (Ming Jong)	M6219 Web Cam	not working (no documentation)	0x0c45	0x60fe	SN9C105
Mikomi (Ming Jong)	M6219Z/MZ Web Cam	not working (no information)			(unknown)
Mikomi (Ming Jong)	M6220 Desktop PC Cam	not working (no information)			(unknown)
Mikomi (Ming Jong)	M6225 Web Cam	should work	0x093a	0x2468	PAC207
Mikomi (Ming Jong)	M6226 Web Cam	not working (no information)			(unknown)
Mikomi (Ming Jong)	M6310 Light Cam	not working (no information)			(unknown)
Mikomi (Ming Jong)	M6311 Light Cam	not working (no information)			(unknown)
Mikomi (Ming Jong)	M6312 PC Cam with microphone and Flexible Mounting Clip	not working (no information)			(unknown)
Mikomi (Ming Jong)	M6313 PC Cam	not working (no information)			(unknown)
Mikomi (Ming Jong)	M632 PC Cam with microphone and Flexible Mounting Clip	not working (no information)			(unknown)
Mikomi (Ming Jong)	M6320 Light Cam	not working (no information)			(unknown)
Mikomi (Ming Jong)	M6321 Light Cam	not working (no information)			(unknown)
Mikomi (Ming Jong)	M6323 Tiny Cam	not working (no information)			(unknown)
Mikomi (Ming Jong)	M6512 Notebook PC Camera	not working (no information)			(unknown)
Mikomi (Ming Jong)	M6515M Web Cam with microphone	not working (no information)			SN9C103
Mikomi (Ming Jong)	M6517 Mobile Web Cam	not working (no information)			(unknown)
Mikomi (Ming Jong)	M6517Z Mobile Web Cam (with digital zoom)	not working (no information)			(unknown)
Mikomi (Ming Jong)	M6522 Notebook PC Camera	not working (no information)			(unknown)
Mikomi (Ming Jong)	M6527 Mobile Web Cam	not working (no information)			(unknown)
Mikomi (Ming Jong)	M6610T Tracking Web Camera	not working (no information)			SQ930B

Mikomi	M6610TM Motion Tracking Web Cam		not working (no			SQ930B
(Ming Jong) Mikomi			information) not working (no			
(Ming Jong) Mikomi	M6620 PC Cam (A)		information) not working (no			M5603C
(Ming Jong)	M6620 PC Cam (B)		information)			DC1100
Minton	Probe 99	Manufacturer	not working (no documentation)			(unknown)
Minton	Probe e.2000	Manufacturer	not working (no documentation)			(unknown)
Minton	S-Cam A2	Manufacturer	not working (no documentation)			(unknown)
Minton	S-Cam F1	Manufacturer	not working (no documentation)			(unknown)
Minton	S-Cam F4	Manufacturer	not working (no documentation)			(unknown)
Minton	S-Cam F5	Manufacturer	works	0x084d	0x0003	SPCA500A
Mitek	CD10		should work			SQ905
Mitek	CD30P		should work			SQ905
MSI	Starcam 370i	Camera	in progress	0x0c45	0x60c0	SN9C105
MSI	StarCam Clip		not working (no documentation)	0x0c45	0x60c0	SN9C102P
MSI	StarCam mini		not working (no information)			(unknown)
MSI	StarCam Sports Football (100K Pixels)		not working (no information)			(unknown)
MSI	StarCam Sports Football (300K Pixels)		not working (no information)			(unknown)
MSI	StarCam Sports_AF		not working (no information)			(unknown)
MtekVision	Zeca MV402		should work			OV511+
Multilaser	Webcam	Supplier	in progress	0x0ac8	0x305b	VC0305
Multilaser	Webcam Olho com Microfone		works	0x04fc	0x0561	SPCA561A
Mustek	Gsm@rt mini 3		in progress			SPCA504A-P3
Mustek	Gsmart mini 2		should work			SPCA504A
Mustek	VC-300		not working (no documentation)			(unknown)
Mustek	WCam 300		in progress	0x06a5	0xd001	NW801
Mustek	WCam 300A	Supplier	should work	0x055f	0xc005	ZC0302
Mustek	WCam 3X		should work			OV511
Neox	NXW-004		in progress	0x0c45	0x6007	SN9C101
NH Japan Holdings	Mach Power SVX	Camera	not working (no documentation)			(unknown)
NHJ Ltd.	TDC-35	Camera	depends (OEM)			SQ905C
Nilox	Neo web cam (W1001 - 640X480)		not working (no information)	?	?	(unknown)
Nilox	PC Video Camera W1002 (WEB CAM 352X288 0,1 MEGAPIXEL)		works	?	?	(unknown)
Nisis	DV4		not working (no camera)	0x08ca	0x0109	ZR36430
Nisis	QuickPix Qp1		should work			STV680
Nisis	QuickPix Qp2		should work			STV680
Nisis	QuickPix Qp3		in progress			SPCA504A
Nogatech	USB Micro Cam		not working (no camera)			NT1003

Nogatech	Video Pro II		not working (no camera)			NT1003
Nortek	Mira		not working (no information)	?	?	(unknown)
Olivetti	WebCam 350K		works			OV519
Optimedia	Afina Eye (new)	Camera	in progress			(unknown)
Oregon Scientific	DS3868		should work			STV680
Oregon Scientific	DS3888 (V-C@m)		should work			STV680
Oregon Scientific	DS3898		should work			STV680
Oregon Scientific	DS3899 (Y-C@m)		should work			STV680
Orite	SC120		should work	0x093a	0x2468	PAC207
Pace	Colour Video Camera		should work			CPiA
Packard Bell	DWC-1		not working (no documentation)			(unknown)
PC Chips	X-eye		should work	0x093a	0x2468	PAC207
PC Line	DC2		not working (no documentation)			(unknown)
PC Line	PCL-100K Webcam		works	0x093a	0x2468	PAC207
PC Line	PCL-300K Webcam	Controller	depends (OEM)	0x0c45	0x62bb	SN9C202
PC Line	PCL-300K Webcam	Controller	depends (OEM)	0x0c45	0x62bb	SN9C202
PC Line	PCL-W300		in progress	0x055f	0xd001	NW801
PC Line	Video Camera (PCL-W310)	Camera	should work			ZC0302
Philips	DMVC 1300K/00		works	0x0471	0x0322	SPCA504B
Philips	PCA645VC		not working (no camera)			(Philips old)
Philips	PCA646VC		not working (no camera)			(Philips old)
Philips	PCVC810B/00 (came with camgoo)		not working (no camera)	0x05a9	0x0518	OV518
Philips	PCVC820 (came with Camgoo)		not working (no camera)	0x05a9	0x0518	OV518
Philips	SIC 4700/37		should work	0x04fc	0x0561	SPCA561A
Philips	SPC 1000NC		depends (UVC)	0x0471	0x0332	(unknown)
Philips	SPC 1300NC		depends (UVC)	0x0471	0x0331	(unknown)
Philips	SPC 200NC	Supplier	works	0x0471	0x0325	VC0305
Philips	SPC 210NC	Supplier	works	0x0471	0x032d	VC0305
Philips	SPC 215NC	Supplier	works	0x0471	0x032d?	VC0305
Philips	SPC 220NC		should work	0x093a	0x2463	PAC207
Philips	SPC 230NC		in progress	0x093a	0x262c	PAC7302
Philips	SPC 300NC	Supplier	works	0x0471	0x0326	VC0305
Philips	SPC 315NC	Supplier	works	0x0471	0x032e	VC0305
Philips	SPC 500NC	Controller	partially works	0x093a	0x2603	PAC7311
Philips	SPC 505NC		not working (no information)			(unknown)
Philips	SPC 520NC		depends (UVC)	0x0471	0x0334	(unknown)
Philips	SPC 525NC		depends (UVC)	0x0471	0x0334	(unknown)
Philips	SPC 530NC		depends (UVC)	0x0471	0x2034	(unknown)
Philips	SPC 600NC		works	0x0471	0x0327	SN9C105
Philips	SPC 610NC	Controller	in progress	0x093a	0x2601	PAC7311
Philips	SPC 620NC		depends (UVC)	0x0471	0x0333	(unknown)

Philips	SPC 650NC		not working (no documentation)	0x0471	0x032f	(unknown)
Philips	SPC 700NC		works	0x0471	0x0328	SN9C105
Philips	SPC 701NC		should work	0x0471	0x0328	SN9C105
Philips	SPC 710NC		in progress	0x0471	0x0330	(unknown)
Philips	SPC 715NC/27 (same as 710NC?)		in progress	0x0471	0x0330	(unknown)
Philips	SPC 900NC	Controller	works	0x0471	0x0329	SAA8116HL
Philips	ToUCam Fun (PCVC730K)	Controller	works			SAA8116HL
Philips	ToUCam Pro	Controller	works			SAA8116HL
Philips	ToUCam Pro (PCVC740K)	Controller	works			SAA8116HL
Philips	ToUCam Pro 3D (PCVC750K)	Controller	should work			SAA8116HL
Philips	ToUcam Pro II (PCVC 840K)		works			(unknown)
Philips	ToUCam Pro II (PCVC 840K)	Controller	works			SAA8116HL
Philips	ToUCam XS (PCVC720K)		should work			OV511
Philips	ToUCam XS (PCVC720K/40)		should work			(unknown)
Philips	Vesta (PCVC675K)	Controller	works			SAA8115HL
Philips	Vesta Fun (PCVC665K)		should work			SE401
Philips	Vesta Pro (PCVC680K)	Controller	works			SAA8115HL
Philips	Vesta Pro Scan (PCVC690K)	Controller	works			SAA8115HL
Philips	VGA FunCam (DMVC300K/00)	Controller	download only			SN9C2028AF
Pico Instruments	iMage [PIKCU03W]	Camera	works (UVC)	0x18cd	Oxcafe	Custom
Plawa	SpyPen		should work			STV680
Plawa	SpyPen Actor		not working (no documentation)			(unknown)
Plawa	SpyPen Axys		should work			STV680
Plawa	SpyPen Cleo		works			STV680
Plawa	SpyPen Luxo		should work			STV680
Plawa	SpyPen Memo		not working (no documentation)			(unknown)
Plawa	SpyPen Memo 1.3		not working (no documentation)			(unknown)
Plawa	SpyPen Xion		works			STV680
Polaroid	PhotoMax PDC 301		in progress	0x0572	0x0040	CX11646
Pound	PC Camera	Controller	depends (OEM)	0x0c45	0x6270	SN9C201
Praktica	MicroPix		works			SQ905
Precision	Mini Digital Camera		should work			SQ905
Premiere	MA88 Digital Microscope Eyepiece		works	0x093a	0x2468	PAC207
Prochips	PCA-3100		should work			OV511+
Puretek	PT-6007		should work			OV511
Qcam	Sports Football		not working (no documentation)	0x06a2	0x6810	TP6810
Qtec	Webcam 100		should work	0x093a	0x2460	PAC207
Radio Shack	Digigr8 (version 1)	Camera	depends (OEM)	0x2770	0x905c	SQ905C
Radio Shack	DigiGr8 (version2)		should work	0x0c45	0x602d	SN9C102
Radio Shack	Kid's Digital Camera	Camera	not working (no documentation)			(unknown)
Rainbow	WebCam Color 5790P [EAN 8436007493774]		not working (no camera)	0x0c45	0x60fe	SN9C105
Rimax	Slim MegaCam 1.3M		not working (no camera)			SPCA504A
Rocketfish	Notebook Web Camera	Camera	depends (OEM)	0x0c45	0x6???	SN9C202
Sakar	GearToGo		should work			SQ905

Sakar	Kidz Cam		should work			SQ905
Sakar	Kidz Cam (new version)	Camera	depends (OEM)			SQ905C
Sakar	PC Microscope [model 72458]		works	0x093a	0x2468	PAC207
Samsung	AnyCam MPC-C10	Controller	in progress			SAA8115HL
Samsung	AnyCam MPC-C30	Controller	in progress			SAA8115HL
Samsung	AnyCam MPC-M10		works			OV511+
Sangha	LTI-355		not working (no documentation)	0x17a1	0x0118	(unknown)
Sangha	SN-510		should work	0x093a	0x2468	PAC207
Sangha	Teddy Cam (T-301)		should work	0x04fc	0x0561	SPCA561A
Sansun	SN-510A		works	0x093a	0x2468	PAC207
Savitmicro	VIJE Talk	Supplier	should work			ZC0302
Sceptre	SVC 300		in progress	0x06a5	0xd001	NW801
Seben	VGA Digital Telescope USB PC Eyepiece (TD35?)		not working (no documentation)	0xeb1a	0x2710	EM2710
Securesight	VL1 digital video recorder		in progress	0x04fc	0x5330	SPCA533A
Shark	SDC-513		should work			SQ905
Shark	SDC-519		should work			SQ905
Shuoying	SY-2107C		should work			SQ905
Sigma	Cam 2000		not working (no camera)	0x0402	0x5603	M5603C
Sigma-Apo	PetCam		should work	0xabcd	Oxcdee	SPCA561A
SilverCrest (Lidl)	50946SC		not working (no documentation)	0xeb1a	0x2710	EM2710
SilverCrest (Lidl)	WC2130	Controller	depends (OEM)	0x0c45	0x62b3	SN9C202
Sitecom	Voicecam USB 2.0 (VP-004)		not working (no information)	?	?	(unknown)
Sitecom	VP-002 Voicecam		should work	0x0c45	0x60af	SN9C103
Smile International	Camera		should work			SPCA501A
Sony	CMR-PC1		not working (no documentation)			(unknown)
Sony	CMR-PC2		not working (no documentation)			(unknown)
Sony	CMR-PC3		not working (no documentation)			(unknown)
Sony	CMR-PC4		not working (no documentation)			(unknown)
Sony	EyeToy USB Camera (SCEH-0004) [silver]		works	0x054c	0x0155	OV519
Sony	HD Eye for PS3 (SLEH 00201) [requires USB2]	Camera	works	0x1415	0x2000	OV538
Sony	laptop (built-in webcam)	Controller	not working (no camera)	0x05ca	0x1832	RY5U870
Sony	laptop (built-in webcam)	Controller	not working (no camera)	0x05ca	0x1836	RY5U870
Sony (Logitech)	EyeToy USB Camera (SLEH-00030)		should work	0x054c	0x0154	OV519
Sony (Namtai)	EyeToy USB Camera (SLEH-00031)		works	0x054c	0x0155	OV519
C-1	Afina Eye	Controller	in progress			SAA8115HL
Sotec	Colden Even CDW 20E	Supplier	works	0x0ac8	0x301b	ZC0301P
Speed	Golden Eyes SPW-205	ouppiio.				
	SPW-202	Supplier	works	0x0ac8	0x301b	ZC0301P

str (School Technology Resources)	ProScope M2		in progress	0x06a5	0xd001	NW801
STX	Pro Series AMT USB Webcam (STX-5007)		in progress	0x0c45	0x613b	SN9C120
Suma	eON		should work			OV511+
SuperCam	WonderEye		should work			CPiA
SUPP	F3 MINI	Manufacturer	not working (no information)			(unknown)
Swann	cheap webcam (with MI360 sensor?)		not working (no documentation)	0x0e61	0x2710	EM2710
Sweda	SmartCam VGAs	Camera	download only			SN9C2028AF
Sweex	foldable webcam		works	0x0c45	0x6011	SN9C101
Sweex	USB Webcam 300K		partially works	0x0c45	0x608f	SN9C103
Takara	PetitShot		should work			STV680
Takara	Slim Shot II		should work			STV680
Targus	USB 2.0 Micro Webcam (AVC05EU)		depends (UVC)			(unknown)
TCE	NetCam 310 USB		works			CPiA
TCE	NetCam 310u		works			OV511
TCM	Dual Mode Camera		works			SPCA504A
TCM	Mini Notebook Camera	Controller	in progress			PAC7311
Technika	VGA Webcam (H16WC-01)		in progress	0x093a	0x262a	PAC7302
TerraTec	TerraCam USB (with snapshot button)		should work			OV511+
TerraTec	TerraCam USB (without snapshot button)		should work			CPiA
TerraTec	TerraCam USB Pro		should work	0x05a9	0xa511	OV511+
TerraTec	TerraCAM USB Pro		in progress	0x05a9	0xa518	OV518+
TerraTec	TerraCam X2		depends (UVC)	0x0ccd	0x0052	(unknown)
TEVion	1.3 MP Webcam (new)	Supplier	in progress	0x0ac8	0x0323	VC0321
TEVion	1.3 MP Webcam (old)		works			(unknown)
TEVion	cheap USB webcam		partially works	0x0c45	0x608f	SN9C103
TEVion	MD 9308		should work			OV511+
Tiger Electronics	VcamNow 2.0		partially works	0x3078	0xA051	SPCA533A
TNC	UW10TNC-1250VUE		works			(unknown)
Tornado	Webcam		should work	0x0c45	0x613c	SN9C120
Toshiba	Camileo Pro		not working (no information)	0x04f2	0xa216	(unknown)
Traveler	Microscope SU 1070 with digital oculair		works			(unknown)
Trust	100 MobileC@m		should work			STV680
Trust	CP-2100		works	0x093a	0x2468	PAC207
Trust	FamilyC@am 300 Flash		should work			STV680
Trust	FunC@m		should work			STV680
Trust	HiRes Webcam Live		works	0x0c45	0x602c	SN9C102
Trust	Mobile Spycam 100		not working (no documentation)	0x0979	0x0224	JL2006B
Trust	Mobile Webcam 100		should work			SQ905
Trust	Sp@ceC@m 100		should work			CPiA
Trust	Sp@ceC@m 150		should work			OV511+
Trust	Sp@ceC@m 200		should work			OV511+
Trust	Sp@ceC@m 300		should work			OV511+
Trust	Sp@ceC@m 350 Portable		not working (no documentation)			(unknown)
Trust	Sp@ceC@m Lite		should work			CPiA
Trust	Sp@ceC@m USB		should work			OV511

Trust	SpaceC@m 120	works	0x0c45	0x600d	SN9C101
Trust	SpaceC@m 150 portable	works			(unknown)
Trust	SpaceC@m 320	works	0x05a9	0x8519	OV519
Trust	SpaceC@m 320	not working (no camera)	0x05a9	0xa518	OV518+
Trust	SpaceCam 100 Portable	in progress	0x06a5	0xd001	NW801
Trust	SpaceCam 120	in progress	0x06a5	0xd001	NW801
Trust	SpyC@m 100	works			STV680
Trust	SpyC@m 100plus	works			STV680
Trust	SpyC@m 300	works			STV680
Trust	SpyC@m 300 Voice	should work			STV680
Trust	SpyC@m XS	should work			STV680
Trust	Usb Webcam WB-6250X	works	?	?	(unknown)
Trust	WB-1200P	should work	0x093a	0x2468	PAC207
Trust	WB-1400T	works	0x093a	0x2468	PAC207
Trust	WB-3100P Portable Webcam	should work	0x0c45	0x60af	SN9C103
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P	in progress	0x0c45	0x613e	SN9C120

Trust	WB-3250P		in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P		in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P		in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P		in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P		in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P		in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P		in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P		in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P		in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P		in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P		in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P		in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P		in progress	0x0c45	0x613e	SN9C120
Trust	WB-3250P		in progress	0x0c45	0x613e	SN9C120
Trust	WB-3270N HiRes Webcam Live		not working (no documentation)	0x145f	0x013b	(unknown)
Trust	WB-3300P	Controller	in progress	0x093a	0x2608	PAC7311
Trust	WB-3320X		in progress	0x093a	0x2621	PAC7302
Trust	WB-3350P	Controller	in progress	0x093a	0x260e	PAC7311
Trust	WB-3400T	Controller	partially works	0x093a	0x2600	PAC7311
Trust	WB-3400T HiRes Webcam		works	0x0c45	0x60af	SN9C103
Trust	WB-3400T HiRes Webcam	Controller	in progress	0x093a	0x260e	PAC7311
Trust	WB-3420N HiRes Webcam Live		not working (no documentation)	0x145f	0x013c	(unknown high-speed)
Trust	WB-3500T USB2 HiRes Webcam		not working (no documentation)	0x2770	0x930c	SQ930C
Trust	WB-5400	Controller	not working (no documentation)	0x0c45	0x624e	SN9C201
Trust	WB-6250X Megapixel USB2 Webcam Live		not working (no camera)	0x145f	0x0142	(unknown)
Trust	Webcam 14823		works	0x0c45	0x6028	SN9C102
TX (Think Xtra)	STX 5007 for Skype		works	?	?	(unknown)
TX (Think Xtra)	STX 5007 for Skype		not working (no camera)	0x0c45	0x613b	(unknown)
TX (Think Xtra)	STX C7 SKYPE Video Starter Pack		in progress	?	?	(unknown)
Typhoon	Webshot II	Supplier	works	0x10fd	0x8050	ZC0301P
Typhoon	Webshot II	Supplier	should work	0x10fd	0x804e	ZC0301P
UMAX	AstraNugget		should work			SQ905
USRobotics	Mini Cam for Skype (USR809640, also 64-809640-00R, 9640)	Controller	depends (OEM)	?	?	SN9C201
Utobia	USB Camera		should work			CPiA
V-GEAR	Talkcam Notebook		not working (no information)	0x114d	0x1100	(unknown)
V-GEAR	TalkCam VX6		depends (OEM)	0x0c45	0x60ec	SN9C102P
Veo	Stingray [330VB39C]		works	0x0545	0x8333	ICM532
ViewQuest	Create and Share (CS330)		works	0x0733	0x0401	SPCA501A
ViewQuest	M318B		should work	0x0733	0x0402	SPCA501A
ViewQuest	PC Camera Pro (CS430)		not working (no camera)	0x0733	0x0430	SPCA505A
ViewQuest	VQ110		works	0x0733	0x0110	SPCA508A
Vimicro / ZSMC	PC Camera ZS211	Manufacturer	works	0x0ac8	0x307b	ZC0301P

Licenced under Creative Common Licence

'isioneer	Communications Primascan i-cam 340		works			(unknown
'isionite	VCS-UC300		in progress			(unknown
'isionite	VCS-UM100		in progress			(unknown
'ivitar	ViviCam 3350		works			SQ905
'ivitar	Vivicam 3350B	Camera	download only			SN9C2028A
ivitar	ViviCam 35	Camera	depends (OEM)			SQ905C
ivitar	ViviCam 5B		should work			SQ905
olcano	DG640E		should work			SQ905
/aitec	Caddy 06		works			(unknown
ebeye/	2000B		should work			OV511+
elback/	C@Mail Hybrid		should work			STV680
elback	CoolCam		should work			STV680
elback/	Digital Camera		should work			STV680
onderEye	CP-115 (newer version - with adjustable focus)		in progress	0x0572	0x0040	CX11646
onderEye	CP-115 (older version)		should work			CPiA
ooritek	Snail Digital Camera		works			(unknown
WL.	Cool-iCam		should work			STV680
WL.	Cool-iCam 2U		should work			STV680
/WL	Cool-iCam Plus		should work			STV680
/WL	Micro Cam		works			STV680
/WL	Pocket Cam		should work			STV680
WL.	Stylus 1000		should work			STV680
/WL	Stylus 1500		should work			STV680
/WL	Stylus 1800		should work			STV680
10	VA11A USB Grabber		works	0x0733	0x0430	SPCA506A
irlink	C-It PC Camera		not working (no documentation)			(unknown
amada	AstraNugget		should work			SQ905
SUNS	PC-320M Plus Webcam	Controller	depends (OEM)	0x0c45	0x6270	SN9C201
ebronics	ZEB 100W (V1)		should work	0x04fc	0x0561	SPCA561
ebronics	ZEB 100W (V2)		should work	0x093a	0x2468	PAC207
oom elephonics	CAM-CU-68R/AM	Manufacturer	works			(unknown
oom elephonics	DualCam 1300 (model 1599)	Manufacturer	not working (no information)	?	?	(unknown
oom elephonics	DualCam 300 (model 1540)	Manufacturer	not working (no information)	?	?	(unknown
oom elephonics	Zoom WebCam USB for Windows (model 1592)	Manufacturer	not working (no documentation)			(unknown
oom elephonics	ZoomCam 100 USB (model 1550)	Manufacturer	not working (no documentation)			(unknown
oom elephonics	ZoomCam USB for Mac (model 1596)	Manufacturer	works			CPiA
oom elephonics	ZoomCam USB for Windows (model 1595, beige case)	Manufacturer	should work			CPiA
oom elephonics	ZoomCam USB II (model 1597, silver case)	Manufacturer	works	0x06a5	0xd001	NW802
oom elephonics	ZoomCam USB III (model 1598, silver case, mic)	Manufacturer	not working (no camera)			OV518

21 of 21 30/09/2021 02:56

Website Design by KPO Expert India